

FORM  
INSPRev  
X/20

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/13/2023

Submitted Date:

09/13/2023

Document Number:

713300102

## FIELD INSPECTION FORM

Loc ID 319310 Inspector Name: Kester, Michael On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 10 Number of Comments  
2 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCinspections@oxy.com	<a href="#">All Inspections</a>
Silver, Randy		randy.silver@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
417187	WELL	SI	08/01/2022	OW	123-31599	DRY CREEK 22-27	SI

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:	good		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	"Sign not legible missing and faded		
Corrective Action:	Install sign to comply with Rule 605.h	Date:	10/13/2023

**Emergency Contact Number:**

Comment:	<input type="text"/>	Date:	<input type="text"/>
Corrective Action:	<input type="text"/>		

**Good Housekeeping:**

Type	OTHER		
Comment:	Protection of soils, stormwater and precipitation cut deep ruts on site and soil run off site		
Corrective Action:	Implement BMP following good engineering practices to minimize stormwater and precipitation. Comply with Rule 1002	Date:	10/13/2023

Overall Good:

**Spills:**

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	SEPARATOR		
Comment:	wire		
Corrective Action:		Date:	

**Equipment:**

Type			corrective date
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	calibration card up to date		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	automation panel		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		

Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 2	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	shared with crude tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	5	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Wells Served By Facilities Above**

API Number
123-31605
123-31600
123-31602

**AirsID**

API Number	AirsID
------------	--------

123-31599
123-31607
123-31606
123-31601

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 417187 Type: WELL API Number: 123-31599 Status: SI Insp. Status: SI**Idle Well**Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Corrective Action:  Date: \_\_\_\_\_**COGCC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary  On Wednesday 9-13-2023 at approximately 12:00, I, Inspector Michael Kester, conducted an on-site inspection.  Location: Dry Creek  Operator: OXY USA  API#: 123-31599  County: Weld  While there, I observed a shut production facility  During this inspection the following possible compliance issues were observed:  NFPA placands, Rule 605h, corrective action date, 10-13-2023, see photo #12  Storm water, Rule 1002, corrective action date 10-13-2023, see photos 1, 2, 3, &amp; 4  Wells and facility are shut in for HOZ PREP  Weather conditions: dry and sunny  A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.  This is a summary of inspection report.</p> <p>This inspection does not nullify any orders or NOAV from the COGCC</p>	kesterm	09/13/2023

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713300103	site pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6249806">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6249806</a>