

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/13/2023

Submitted Date:

09/13/2023

Document Number:

697008024

FIELD INSPECTION FORMLoc ID 433845 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|--------------------------|---------|
| , | | cogccinspection@pdce.com | |

General Comment:

Location

Overall Good: ☒

| | | | |
|----------------------|---|-------|------------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | x 8 | | |
| Corrective Action: | | Date: | |
| Type | CONTAINERS | | |
| Comment: | Chemical system at wellhead lacks placards, see attached photo. | | |
| Corrective Action: | Install sign to comply with Rule 605.h. | Date: | 10/16/2023 |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|---|-------|------------|
| Type | UNUSED EQUIPMENT | | |
| Comment: | Unused chemical rack, see attached photo. | | |
| Corrective Action: | Comply with Rule 606. | Date: | 10/16/2023 |

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|----------|-------|--|
| Type | WELLHEAD | | |
| Comment: | Panel | | |
| Corrective Action: | | Date: | |

Equipment:

corrective date

| | | | |
|---------------------------|--|-------|--|
| Type: Plunger Lift | # 8 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 8 | | |
| Comment: | Bradenhead valves are exposed at surface. | | |
| Corrective Action: | | Date: | |
| Type: Flow Line | # 8 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # | | |
| Comment: | Chemical and methanol systems in secondary containment | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | | |
|---|---|----------|---------------------|---------|--------|--|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| | | | CENTRALIZED BATTERY | | , | |
| Comment: Tank battery #442936 | | | | | | |
| Corrective Action: | | | | | Date: | |

Paint

| | | |
|------------------|--|--|
| Condition | | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|--|-----------|------------|
| <p>COGCC Inspection Report Summary On Wednesday 9/13/2023 at approximately 14:40 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the PDC Energy Tailholt FD Pad 11-25HN location #433845 in Weld County, Colorado. While there, I observed that a chemical system lacked placards and unused equipment on location. The following possible compliance issues were observed: Rule 605.h. with a corrective action date of 10/16/2023, Rule 606. with a corrective action date of 10/16/2023. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the inspection report.</p> | petersont | 09/13/2023 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 697008025 | Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6249963 |