

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/23/2023

Submitted Date:

08/23/2023

Document Number:

679606137**FIELD INSPECTION FORM**Loc ID 430616 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCInspections@Oxy.co m	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
430615	WELL	SI	04/01/2021	OW	123-36212	BYDALEK 28C-20HZ	TA
430618	WELL	SI	02/01/2021	OW	123-36214	BYDALEK 4N-20HZ	TA
430620	WELL	SI	02/01/2021	OW	123-36216	BYDALEK 28N-20HZ	TA
430622	WELL	SI	10/01/2020	OW	123-36217	BYDALEK 3N-20HZ	TA
430624	WELL	PR	09/12/2013	OW	123-36219	BYDALEK 29C-20HZ	PR
430626	WELL	PR	02/01/2020	OW	123-36220	BYDALEK 29N-20HZ	PR
430629	WELL	PR	09/12/2013	OW	123-36223	BYDALEK 30C-20HZ	TA

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	unused/disconnected equipment on location. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	10/07/2023

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	iron		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	wire		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	iron		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	wire		
Corrective Action:		Date:	

Equipment:				corrective date	
Type: Bradenhead	# 7				
Comment:					
Corrective Action:					Date:
Type: Plunger Lift	# 2				
Comment:					
Corrective Action:					Date:
Type: Pump Jack	# 5				
Comment:					
Corrective Action:					Date:
Type: Compressor	# 1				
Comment:					
Corrective Action:					Date:
Type: Gas Meter Run	# 3				
Comment:					
Corrective Action:					Date:
Type: Bird Protectors	# 8				
Comment:					
Corrective Action:					Date:
Type: Emission Control Device	# 1				
Comment:					
Corrective Action:					Date:
Type: Horizontal Heated Separator	# 7				
Comment:					
Corrective Action:					Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	OTHER	PBV FIBERGLASS		,	
Comment:						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)		210 BBLS				
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:		Shares containment with other tanks.				
Corrective Action:						Date:
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
Flaring:						
Type						
Comment:						
Corrective Action:						Date:

Inspected FacilitiesFacility ID: 430615 Type: WELL API Number: 123-36212 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTEDComment: Corrective Action: Date: Facility ID: 430618 Type: WELL API Number: 123-36214 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTEDComment: Corrective Action: Date: Facility ID: 430620 Type: WELL API Number: 123-36216 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTEDComment: Corrective Action: Date: Facility ID: 430622 Type: WELL API Number: 123-36217 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTEDComment: Corrective Action: Date: Facility ID: 430624 Type: WELL API Number: 123-36219 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: Facility ID: 430626 Type: WELL API Number: 123-36220 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: Facility ID: 430629 Type: WELL API Number: 123-36223 Status: PR Insp. Status: TA

<u>Idle Well</u>		
Purpose:	<input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned	Reminder: EQUIPMENT PRESENT/DISCONNECTED
<u>Comment:</u>	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>**Weather Conditions: sunny, dry ground</p> <p>On Wednesday, August 23, 2023 at approximately 12:30, I, Inspector Brittani Santistevan, conducted an on-site inspection at BYDALEK 28C-20HZ (Kerr McGee Oil & Gas Onshore), at location #: 430616 in WELD COUNTY Colorado.</p> <p>While there, I observed a shut in facility.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>1. It appears to be unused/disconnected equipment near wellheads. Reconnect or remove from location per Rule 606. (Corrective Action Date: October 7, 2023) See attached photo #3-8.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	santistb	08/23/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403523019	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6244083
679606138	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6244043