

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/06/2023

Submitted Date:

09/07/2023

Document Number:

713600203

FIELD INSPECTION FORMLoc ID 314177 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 74165

Name of Operator: RENEGADE OIL & GAS COMPANY LLC

Address: 6155 S MAIN STREET #225

City: AURORA State: CO Zip: 80016

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Sanchez, Chris		chris.sanchez@state.co.us	
INGVE EDWARD		ed@renegadeoilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
227737	WELL	PR	12/01/2021	GW	099-06063	IDLER C 1	RI
447057	TANK BATTERY	AC	07/29/2016		-	IDLER C-622S47W 29SWSW	RI

General Comment:

On 9/6/2023, Ryan Costa conducted a follow up location inspection.
See attached photos and additional details within this report.

Previous corrective actions have not been completed and additional issues have been observed.
Operator is directed to perform corrective actions outlined on this inspection report immediately.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	The open top tank labeling is inaccurately posted as produced water and there is crude oil in the tank. Previous corrective action was not completed.		
Corrective Action:	Install sign to comply with Rule 605.h. and accurately show contents in the tank.	Date:	07/11/2023

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
Crude Oil	Tank			
Comment:	There is oil stained soils at the two tanks and at the pipe outlet. It appears part of the stained soils were dug up by the tank and dumped on the ground which is causing further contamination of soils. E&P waste must be properly cleaned up and disposed per Rule 905. Previous corrective action was not completed.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.			Date: 07/12/2023

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:	The fence around the tank battery is in disrepair.		
Corrective Action:	Comply with the fencing requirements per the 1002a rules		
		Date:	09/06/2023

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1		Open Top		,	
Comment:	The netting on the open top tank is insufficient to prevent wildlife entry. Previous corrective action was not completed.					
Corrective Action:	Install or repair wildlife protection equipment.					Date: 07/11/2023

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403523378	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6244447
713600204	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6244435