

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/13/2023

Submitted Date:

09/13/2023

Document Number:

707601831

FIELD INSPECTION FORMLoc ID 302380 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298347	WELL	TA	12/01/2019	GW	123-29039	SCHMIER B 32-32	TA

General Comment:

This is a WELL inspection.

Well(s): 1: Temporarily Abandoned | TA.

Battery: Inactive | Shut-down.

Centralized Battery serves 2 Location IDs
(336634, 302380).

(Well(s): 3: Temporarily Abandoned | TA ;1: Plugged & Abandoned | PA).

Centralized Battery formerly served 2 Location IDs
(305730, 327645).

(Well(s): 2: Plugged & Abandoned | PA).

Centralized Battery serves 1 Tank Battery Facility ID
(447717).

(Battery: Inactive | Shut-down).

Reference:A.) Field Inspection Report doc. #707601829 and/or Location ID #336634
for TA Well(s) info. (2).B.) Field Inspection Report doc. #707601831 and/or Location ID #302380
for TA Well(s) info. (1).C.) Field Inspection Report doc. #707601833 and/or Location ID #336634
for PA Well(s) info. (1).D.) Field Inspection Report doc. #707601835 and/or Location ID #305730
for PA Well(s) info. (1).E.) Field Inspection Report doc. #707601837 and/or Location ID #327645
for PA Well(s) info. (1).F.) Field Inspection Report doc. #707601839 and/or Facility ID #447717
for Battery / Facility, Equipment info.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Wellhead w/ Master, casing valves.		
Corrective Action:		Date:	
Type: Plunger Lift	# 0		
Comment:	Temporarily Abandoned TA. Equipment removed.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.359546,-104.582714

Comment:	Centralized Battery serves 2 Location IDs (336634, 302380). (Well(s): 3: Temporarily Abandoned TA). Centralized Battery serves 1 Tank Battery Facility ID (447717). (Battery: Inactive Shut-down).	
Corrective Action:		Date:

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 298347 Type: WELL API Number: 123-29039 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Disconnected from flowlie.
Locked-Out, Tagged-Out | LOTO.
Blue TA tag posted.
CECMC records last prod: 03/2019.

Form 4 on file. TA date: 03/11/2019. Approved.
DH-CIBP set.
Form 21 MIT on file. MIT date: 08/06/2019. Approved.
Form 6A on file. Out-of-Svc Designation.
Date: 09/28/2021. Approved.

Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 07/09/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>CECMC Inspection Report Summary:</p> <p>On WED 09/13/2023 at approximately 14:37 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Location Name: SCHMIER B-65N64W/32SWNW Location ID: 302380 Well Name(s): Schmier B 32-32. API: 123-29039. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 2 Location IDs (336634, 302380). (Well(s): 3: Temporarily Abandoned TA ;1: Plugged & Abandoned PA).</p> <p>Centralized Battery formerly served 2 Location IDs (305730, 327645). (Well(s): 2: Plugged & Abandoned PA).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (447717). (Battery: Inactive Shut-down).</p> <p>Reference: A.) Field Inspection Report doc. #707601829 and/or Location ID #336634 for TA Well(s) info. (2). B.) Field Inspection Report doc. #707601831 and/or Location ID #302380 for TA Well(s) info. (1). C.) Field Inspection Report doc. #707601833 and/or Location ID #336634 for PA Well(s) info. (1). D.) Field Inspection Report doc. #707601835 and/or Location ID #305730 for PA Well(s) info. (1). E.) Field Inspection Report doc. #707601837 and/or Location ID #327645 for PA Well(s) info. (1). F.) Field Inspection Report doc. #707601839 and/or Facility ID #447717 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	09/13/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707601832	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6250182