

Inspection Photos
Location Name: CAERUS PICEANCE LLC O18 Pad
Location #: 311604



Photo # 8842 From entrance to location



Photo # 8843 From entrance to location

Inspection Photos
Location Name: CAERUS PICEANCE LLC O18 Pad
Location #: 311604



Photo # 8844 Location



Photo # 8845 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC O18 Pad
Location #: 311604



Photo # 8846 Location



Photo # 8847 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC O18 Pad
Location #: 311604



Photo # 8851 Open ended load line



Photo # 8852 Debris

Inspection Photos
Location Name: CAERUS PICEANCE LLC O18 Pad
Location #: 311604



Photo # 8859 Debris



Photo # 8860 Debris

Inspection Photos
Location Name: CAERUS PICEANCE LLC O18 Pad
Location #: 311604



Photo # 8861 Debris



Photo # 8857 Stained gravel

Inspection Photos
Location Name: CAERUS PICEANCE LLC O18 Pad
Location #: 311604



Photo # 8862 Hole in secondary containment liner/liner needs maintenance



Photo # 8863 Hole in secondary containment liner/liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC O18 Pad
Location #: 311604



Photo # 8865 Hole in secondary containment liner/liner needs maintenance



Photo # 8866 Hole in secondary containment liner/liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC O18 Pad
Location #: 311604



Photo # 8867 Holes in secondary containment liner/liner needs maintenance



Photo # 8868 Hole in secondary containment liner/liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC O18 Pad
Location #: 311604



Photo # 8867 Holes in secondary containment liner/liner needs maintenance



Photo # 8869 Hole in secondary containment liner/liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC O18 Pad
Location #: 311604



Photo # 8870 Tank battery lacks required signage



Photo # 8871 Tank battery lacks required signage

Inspection Photos
Location Name: CAERUS PICEANCE LLC O18 Pad
Location #: 311604



Photo # 8877 Debris



Photo # 8879 Debris

Inspection Photos
Location Name: CAERUS PICEANCE LLC O18 Pad
Location #: 311604



Photo # 8884 Debris