

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/14/2023

Submitted Date:

09/15/2023

Document Number:

705000432

FIELD INSPECTION FORMLoc ID 327695 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		COGCCInspections@Oxy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
247238	WELL	SI		OW	123-15035	UPRC 17-11J	PA
247239	WELL	SI	04/01/2022	OW	123-15036	UPRC 17-14J	PA
327695	LOCATION	AC			-	UPRC-63N65W 17SESW	EG

General Comment:COGCC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Inspected Facilities

Facility ID: 247238 Type: WELL API Number: 123-15035 Status: SI Insp. Status: PA

Facility ID: 247239 Type: WELL API Number: 123-15036 Status: SI Insp. Status: PA

Flowline

#1	Type: Non-Well Site	of Lines
----	---------------------	----------

Flowline Description

Flowline Type: Non-Well Site Size: 2" Material: Carbon Steel
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: (2) wells are plugged and abandoned (UPRC 17-11J, 14J); ECMC form 42 notices of start of plugging operations received April 2023. Off location flowlines between area (PA) wells and facility/ battery have been removed; ECMC form 42 notices of flowline abandonment (removal) completed received 08/31/2023. The facility/ tank battery has been decommissioned; tanks and equipment removed. Fenced excavations observed on location at battery/ equipment areas. On location dump and process flowlines at facility/ battery have been removed. Remediation work (per form 27) is in progress.

Corrective Action:

Date:

Facility ID: 327695 Type: LOCATION API Number: - Status: AC Insp. Status: EG

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000433	Fenced excavation at battery; signage	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6252873
705000434	PA well and signage	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6252874