

# Inspection Photos

Loc: 418506

Operator: OXY USA INC

Inspection Date: 9/13/2023

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing east along the access road. The cattle guard is filled in with sediment and erosion is occurring at this area.





## Inspection Photos



**Photo 2.** Facing east at the location..



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:418506 | Date: 9/13/2023



## Inspection Photos



**Photo 3.** Well sign is posted at the meter shed.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:418506 | Date: 9/13/2023



## Inspection Photos



**Photo 4.** Facing northeast toward the interim reclamation area cut slope.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:418506 | Date: 9/13/2023



## Inspection Photos



**Photo 5.** Facing northwest toward the interim reclamation area. Perennial vegetation is progressing.

