


Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC MOBIL GV 11-33 Pad
Location ID: 323824



Location Overview: Location is within High Priority/Density/Black Bear Habitat areas & Bald Eagle Roost Site & in close proximity to NSO Habitat area. Location is within Rule 411a Surface Water Intermediate Buffer. Location is approximately 434 yards from the Colorado River.

Section/Township/Range: 33 6S95W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC MOBIL GV 11-33 Pad
Location ID: 323824



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC MOBIL GV 11-33 Pad
Location ID: 323824



Photo # Erosion & transport of sediment

Photo # Erosion & transport of sediment

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC MOBIL GV 11-33 Pad
Location ID: 323824



Photo # 9127 Erosion & transport of sediment



Photo # 9128 Erosion & transport of sediment

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC MOBIL GV 11-33 Pad
Location ID: 323824



Photo # 9131 Erosion & transport of sediment



Photo # 9132 Erosion & transport of sediment off location into a vegetated area/choking off vegetation/insufficient BMP's .

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC MOBIL GV 11-33 Pad
Location ID: 323824



Photo # 9134 Erosion & transport of sediment off location into a vegetated area/choking off vegetation/insufficient BMP's .

Photo # 9135 Erosion & transport of sediment off location into a vegetated area/choking off vegetation/insufficient BMP's .

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC MOBIL GV 11-33 Pad
Location ID: 323824



Photo # 9136 Erosion & transport of sediment off location into a vegetated area/choking off vegetation/insufficient BMP's .

Photo # 9137 Erosion & transport of sediment off location into a vegetated area/choking off vegetation/insufficient BMP's .

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC MOBIL GV 11-33 Pad
Location ID: 323824



Photo # 9138 Erosion & transport of sediment off location into a vegetated area/choking off vegetation/insufficient BMP's .



Photo # Erosion & transport of sediment off location into a vegetated area/choking off vegetation/insufficient BMP's .

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC MOBIL GV 11-33 Pad
Location ID: 323824



Photo # 9140 Erosion & transport of sediment off location into a vegetated area/choking off vegetation/insufficient BMP's .

Photo # 9141 Erosion & transport of sediment off location into a vegetated area/choking off vegetation/insufficient BMP's .

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC MOBIL GV 11-33 Pad
Location ID: 323824



Photo # 9142 Erosion & transport of sediment off location into a vegetated area/choking off vegetation/insufficient BMP's .

Photo # 9143 Erosion & transport of sediment off location into a vegetated area/choking off vegetation/insufficient BMP's .

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC MOBIL GV 11-33 Pad
Location ID: 323824



Photo # 9147 Erosion & transport of sediment off location into a vegetated area/choking off vegetation/insufficient BMP's .

Photo # 9151 Erosion & transport of sediment off location into a vegetated area/choking off vegetation/insufficient BMP's .

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC MOBIL GV 11-33 Pad
Location ID: 323824



Photo # 9159 Erosion & transport of sediment off location into a vegetated area/choking off vegetation/insufficient BMP's .



Photo # 9161 Erosion & transport of sediment off location into a vegetated area/choking off vegetation/insufficient BMP's .

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC MOBIL GV 11-33 Pad
Location ID: 323824



Photo # 9152 Erosion & transport of sediment off location into a vegetated area/choking off vegetation/insufficient BMP's .



Photo # 9153 Erosion & transport of sediment off location into a vegetated area/choking off vegetation/insufficient BMP's .

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC MOBIL GV 11-33 Pad
Location ID: 323824



Photo # 9154 Erosion & transport of sediment off location into a vegetated area/choking off vegetation/insufficient BMP's .

Photo # 9155 Erosion & transport of sediment off location into a vegetated area/choking off vegetation/insufficient BMP's .