

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/17/2023

Submitted Date:

08/17/2023

Document Number:

713300016

**FIELD INSPECTION FORM**Loc ID 332979 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name  | Phone | Email                    | Comment                         |
|---------------|-------|--------------------------|---------------------------------|
| , General     |       | COGCC@KPK.com            | <a href="#">All Inspections</a> |
| Silver, Randy |       | randy.silver@state.co.us |                                 |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name                | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------------|-------------|
| 242322      | WELL | SI     | 05/01/2021  | GW         | 123-10113 | WATTENBERG HENRY E<br>UT B 2 | SI          |

**General Comment:**

**Location**Overall Good: ☒

|                      |          |       |  |
|----------------------|----------|-------|--|
| <b>Signs/Marker:</b> |          |       |  |
| Type                 | WELLHEAD |       |  |
| Comment:             | good     |       |  |
| Corrective Action:   |          | Date: |  |

|                           |  |  |             |
|---------------------------|--|--|-------------|
| Emergency Contact Number: |  |  |             |
| Comment:                  |  |  |             |
| Corrective Action:        |  |  | Date: _____ |

|                           |  |       |            |
|---------------------------|--|-------|------------|
| <b>Good Housekeeping:</b> |  |       |            |
| Type                      | WEEDS  |       |            |
| Comment:                  | over grown vegation on location and around equipment   |       |            |
| Corrective Action:        | Complie with Rule 606  | Date: | 09/17/2023 |
| Type                      | OTHER  |       |            |
| Comment:                  | mechanical issues, equipment in disrepair, pumping unit has not prime mover  |       |            |
| Corrective Action:        | Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. | Date: | 09/17/2023 |
| Type                      | UNUSED EQUIPMENT   |       |            |
| Comment:                  | Pumping unit has no prime move, concidered as unused equipment   |       |            |
| Corrective Action:        | Complie with Rule 606  | Date: | 09/17/2023 |

Overall Good: ☐

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

|                    |     |       |                 |
|--------------------|-----|-------|-----------------|
| <b>Equipment:</b>  |     |       | corrective date |
| Type: Pump Jack    | # 1 |       |                 |
| Comment:           |     |       |                 |
| Corrective Action: |     | Date: |                 |

|                    |    |       |  |
|--------------------|----|-------|--|
| <b>Venting:</b>    |    |       |  |
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

|                 |  |  |  |
|-----------------|--|--|--|
| <b>Flaring:</b> |  |  |  |
| Type            |  |  |  |
| Comment:        |  |  |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| Corrective Action: |  | Date: |  |
|--------------------|--|-------|--|

**Inspected Facilities**Facility ID: 242322 Type: WELL API Number: 123-10113 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: PRODUCTION RECORDSComment: Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well.Corrective Action: Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.Date: 09/17/2023**BradenHead**Date of Last Brhd Test: 08/22/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**COGCC Comments**

| Comment   | User    | Date       |
|---|---------|------------|
| <p>ECMC Inspection Report Summary</p> <p>On Thursday 8-17-23 at approximately 10:30, I, Inspector Michael Kester, conducted an on-site inspection.</p> <p>Location:Wattenburg Henery E UT B#2</p> <p>Operator: KP Kaufman</p> <p>API#: 123-10113</p> <p>County: Weld</p> <p>While there, I observed shut in well site</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Weeds; Rule 606 corrective action date 9-17-23 See photo 2 &amp; 3</p> <p>Mechanical issues: rule 608E corrective action date 9-17-23 See photo 4</p> <p>Unused equipment: Rule 606 corrective action date 9-17-23 See photo 2</p> <p>MIT; Rule 417B corritive action date 9-17-23</p> <p>Weather conditions: Dry &amp; Clear</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p> <p>This is a summary of inspection report.</p> | kesterm | 08/17/2023 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 403526083    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6247272">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6247272</a> |
| 713300017    | Site pic             | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6247229">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6247229</a> |