

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/23/2023

Submitted Date:

08/23/2023

Document Number:

713300036

FIELD INSPECTION FORMLoc ID 318403 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

10 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	ALL INSPECTIONS
Silver, Randy		randy.silver@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241233	WELL	SI	05/01/2023	GW	123-09021	CAVANAUGH, FRANK M 3	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Good Housekeeping:		
Type	WEEDS	
Comment:	overgrown vegataion	
Corrective Action:	comply rule 606	Date: 08/30/2023

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:		
Type	WELLHEAD	
Comment:	metal panels	
Corrective Action:		Date:
Type	OTHER	
Comment:	electrical panel fence metal panels	
Corrective Action:		Date:
Type	PUMP JACK	
Comment:	metal panels	
Corrective Action:		Date:

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	eletrical panel		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	

Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
<u>Venting:</u>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
<u>Flaring:</u>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 241233 Type: WELL API Number: 123-09021 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: PRODUCTION RECORDSComment: at time of inspection well appered to be shut inCorrective Action: Date: **BradenHead**Date of Last Brhd Test: 03/28/2023Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date: **COGCC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Wednesday 8-23-23 at approximately 14:00, I, Inspector Michael Kester, conducted an on-site inspection.</p> <p>Location: Cavanaugh Frank M 3</p> <p>Operator: KPK</p> <p>API#: 123-09021</p> <p>County: Weld</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Weeds, Rule 606, corrective date 8-30-2023</p> <p>See attached photo # 1, 2, 3, & 4</p> <p>Weather conditions: Dry and sunny</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p> <p>This is a summary of inspection report.</p> <p>This inspection does not nullify any orders or NOAV from the COGCC</p>	kesterm	08/23/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403526097	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6247284
713300037	site pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6247238