

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/11/2023

Submitted Date:

09/12/2023

Document Number:

712700639

FIELD INSPECTION FORMLoc ID 326426 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

17 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, General		FarmingtonRegulatoryTechs@hilcorp.com	All SW Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216475	WELL	PR	10/01/2018	CBM	067-08081	WILSON 34-9 29-1	PR

General Comment:

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

The separators and meter run equipment for both the Wilson #29-1 and Wilson #29-4 are located in the same fenced area just east of Hwy 550 south.

Location			
Lease Road:			
Type	Access		
comment:	Gated off of private road.		
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Fenced location signed.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Metal sign posted at location fencing.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Posted on wellhead sign.		Date: _____
Corrective Action:			
Good Housekeeping:			
Type	WEEDS		
Comment:	Undesirable plant species growing throughout fenced location. See Photos #2-#4.		
Corrective Action:	Remove weeds from within fenced location per Rule 606.c.		Date: 09/19/2023
Type	DEBRIS		
Comment:	Thick growths of weedy vegetation growing around separators. See Photos #2-#4.		
Corrective Action:	Remove combustible debris 25 feet from fired equipment per Rule 610.k.		Date: 09/15/2023
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	LOCATION		
Comment:	6-ft chainlink with privacy panels.		
Corrective Action:			Date:
Equipment:			
Type: Gas Meter Run	# 1		corrective date
Comment:	Calibration date 1/10/2023.		
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:			

Corrective Action:		Date:	
Type: Bird Protectors	#		
Comment:	On separator vent stack.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electrical boxes, service panels, meters and gauges.		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:	Cohoused with meter run.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric motor and water transfer equipment.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	216475	Type:	WELL	API Number:	067-08081	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	04/25/2023	Annual Brhd Completed?	Yes						
Last Brhd Test Results	Initial Surf Csg Pressure:	0	Fluid Type:						
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Ditches	Pass			
Gravel	Pass	Gravel	Pass			

Comment: [No visible erosion or sediment migration observed during inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403526870	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6247993
712700643	Well Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6247984