

Inspection Photos

Loc: 309313

Operator: XTO ENERGY INC

Inspection Date: 9/18/2023

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing north at the beginning of the access road. There is sediment deposition at the cattleguard and roadside from recent rainstorms..



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:309313 | Date: 9/18/2023

Inspection Photos



Photo 2. Facing north along the access road. Stormwater has washed around the rock checkdams shown at red arrow.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:309313 | Date: 9/18/2023

Inspection Photos



Photo 3. Facing back south at the access road. There is erosion along the road from recent rain storms.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:309313 | Date: 9/18/2023

Inspection Photos



Photo 4. Facing northwest along the access road. There is an erosion channel along the road beginning to develop. BMP's such as a water bar may help direct stormwater off the road.



Inspection Photos



Photo 5. Facing northwest toward the location. Additional rock rip rap was installed in this area.



Inspection Photos



Photo 6. Facing northwest. There is erosion beginning to occur in this area bare of vegetation. Additional BMPs should be installed until vegetation establishes.



Inspection Photos



Photo 7. Facing southwest. There is erosion beginning to occur in this area bare of vegetation. Additional BMPs should be installed until vegetation establishes.



Inspection Photos



Photo 8. South side of the location facing north. Overall vegetation appears to be progressing.



Inspection Photos



Photo 9. South side of the location facing northwest. Overall vegetation appears to be progressing.



Inspection Photos



Photo 10. Center of the location facing east. This area was disturbed and will need to re-establish perennial vegetation.



Inspection Photos



Photo 11. Facing northwest toward the west side of the location. Additional rock rip/rap was installed in this area.

