

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/13/2023

Submitted Date:

09/13/2023

Document Number:

707601839

FIELD INSPECTION FORM

Loc ID: 447718 Inspector Name: Evins, Bret On-Site Inspection: 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

13 Number of Comments

2 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
447717	TANK BATTERY	AC	09/12/2016		-	SCHMIER-65N64W 32NWNW	IO

General Comment:

This is a TANK BATTERY inspection.
Associated Well(s): 3: Temporarily Abandoned | TA.
Battery: Inactive | Shut-down.

Centralized Battery serves 2 Location IDs (336634, 302380).
(Well(s): 3: Temporarily Abandoned | TA ;1: Plugged & Abandoned | PA).

Centralized Battery formerly served 2 Location IDs (305730, 327645).
(Well(s): 2: Plugged & Abandoned | PA).

Centralized Battery serves 1 Tank Battery Facility ID (447717).
(Battery: Inactive | Shut-down).

Reference:

A.) Field Inspection Report doc. #707601829 and/or Location ID #336634 for TA Well(s) info. (2).
B.) Field Inspection Report doc. #707601831 and/or Location ID #302380 for TA Well(s) info. (1).
C.) Field Inspection Report doc. #707601833 and/or Location ID #336634 for PA Well(s) info. (1).
D.) Field Inspection Report doc. #707601835 and/or Location ID #305730 for PA Well(s) info. (1).
E.) Field Inspection Report doc. #707601837 and/or Location ID #327645 for PA Well(s) info. (1).
F.) Field Inspection Report doc. #707601839 and/or Facility ID #447717 for Battery / Facility, Equipment info.

Location			
Lease Road:			
	Type Access		
comment:	Adequate		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
	Type TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
	Type BATTERY		
Comment:	Sign w/ Emergency number, Company, & Well names NOT posted at Battery site. Refer to Rule 605.e for guidance.		
Corrective Action:	*Post sign w/ Emergency number, Company & Well names at Battery site. Comply with Rule 605.e. Corrective Action date: 10/16/2023. (30-days). See photo #1. *Attach photo(s) to FIRR to verify Corrective Action(s) have been resolved.		Date: 10/16/2023
Emergency Contact Number:			
Comment:	Sign w/ Emergency number, Company, & Well names NOT posted at Battery site. Refer to Rule 605.e for guidance.		
Corrective Action:	*Post sign w/ Emergency number, Company & Well names at Battery site. Comply with Rule 605.e. Corrective Action date: 10/16/2023. (30-days). See photo #1. *Attach photo(s) to FIRR to verify Corrective Action(s) have been resolved.		Date: 10/16/2023
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
	Type TANK BATTERY		
Comment:	Braided wire.		
Corrective Action:		Date:	
	Type SEPARATOR		

Comment: Surrounded by earth berms.			
Corrective Action:		Date:	
Equipment:			corrective date
Type: Gas Meter Run	# 2		
Comment: Gas Sales. Calibration card(s) indicates calibration > 1 year. Last calibration: 03/25/2020. Inactive. NO production.			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment: 1: Crude storage vapor line combustor(s). Controls crude oil tank(s) vapors. Pilots: OFF. Shut-down. 1: Separator vapor line combustor(s). Controls separator(s) vapors. Pilots: OFF. Shut-down.			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment: Centralized Battery serves 2 Location IDs (336634, 302380). (Well(s): 3: Temporarily Abandoned TA). Centralized Battery serves 1 Tank Battery Facility ID (447717). (Battery: Inactive Shut-down).					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	300 BBLS	STEEL AST		40.359546,-104.582714
Comment:					
Corrective Action:					Date:

Paint	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:	Berms shared w/ crude oil, produced H2O tank(s).			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	<100 BBLS	CONCRETE SUMP/VAULT		,
Comment:					
Corrective Action:					Date:

Paint	
Condition	
Other (Content)	
Other (Capacity)	60 Bbls.
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:	Berms shared w/ crude oil, produced H2O tank(s).			
Corrective Action:				Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:	
Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 447717 Type: TANK API Number: - Status: AC Insp. Status: IO

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>CECMC Inspection Report Summary:</p> <p>On WED 09/13/2023 at approximately 15:12 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Facility Name: SCHMIER-65N64W/32NWNW Facility ID: 447717 Location Name: SCHMIER-65N64W/32NWNW Location ID: 336634 Associated Well Name(s): 3: Temporarily Abandoned TA. Schmier B 32-30D, Schmier B 32-31D, Schmier B 32-32. API: 123-29003, 123-29659, 123-29039. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Associated Well(s): 3: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 2 Location IDs (336634, 302380). (Well(s): 3: Temporarily Abandoned TA ;1: Plugged & Abandoned PA).</p> <p>Centralized Battery formerly served 2 Location IDs (305730, 327645). (Well(s): 2: Plugged & Abandoned PA).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (447717). (Battery: Inactive Shut-down).</p> <p>Reference: A.) Field Inspection Report doc. #707601829 and/or Location ID #336634 for TA Well(s) info. (2). B.) Field Inspection Report doc. #707601831 and/or Location ID #302380 for TA Well(s) info. (1). C.) Field Inspection Report doc. #707601833 and/or Location ID #336634 for PA Well(s) info. (1). D.) Field Inspection Report doc. #707601835 and/or Location ID #305730 for PA Well(s) info. (1). E.) Field Inspection Report doc. #707601837 and/or Location ID #327645 for PA Well(s) info. (1). F.) Field Inspection Report doc. #707601839 and/or Facility ID #447717 for Battery / Facility, Equipment info.</p> <p>During this inspection the following possible compliance issue(s) were observed: 1.) Sign w/ Emergency number, Company, & Well names NOT posted at Battery site. Refer to Rule 605.e for guidance. *Post sign w/ Emergency number, Company & Well names at Battery site. Comply with Rule 605.e. Corrective Action date: 10/16/2023. (30-days). See photo #1.</p> <p>*Attach photo(s) to FIRR to verify Corrective Action(s) have been resolved.</p> <p>*A follow up on this site inspection will be conducted to ensure that compliance issues have been corrected to comply with CECMC rules.</p> <p>This is a summary of the inspection report.</p>	<p>evinsb</p>	<p>09/13/2023</p>

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403529387	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6250187
707601840	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6250186