

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/14/2023

Submitted Date:

09/15/2023

Document Number:

712700658

**FIELD INSPECTION FORM**Loc ID 333826 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

20 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		FarmingtonRegulatoryTechs@hilcorp.com	All SW Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258094	WELL	PR	12/27/2000	CBM	067-08322	ARGENTA 33-10 4-3	PR

**General Comment:**

SW Compliance Specialist Curtis Pattillo conducted a follow up field inspection to verify completion of corrective actions identified in FIR Document #712700450 submitted 8/2/2023.

New corrective actions identified in this FIR, See Housekeeping section.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Graveled. Approaching the well location the road is being overgrown by Kochia, becoming a two-track.		
Corrective Action		Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Warning signs posted on pumpjack.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Contents and volume labels, NFPA placard.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Metal sign posted at meterhouse.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Posted on wellhead sign.

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Observed impacted material on ground at the wellhead and at the muffler outlet of the prime mover. See Photos #3-#5.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002..(2).D.	Date:	09/19/2023
Type	STORAGE OF SUPL		
Comment:	Corrective action identified in FIR Doc.#712700450 has been completed.		
Corrective Action:		Date:	

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	
In Containment:	No		
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Angle iron cage.		
Corrective Action:		Date:	

<b>Equipment:</b>				corrective date	
Type: Gathering Line	# 1				
Comment:	Buried valve can				
Corrective Action:				Date:	
Type: Ancillary equipment	# 1				
Comment:	Cathodic protection with solar panel.				
Corrective Action:				Date:	
Type: Ancillary equipment	# 1				
Comment:	Wellhead				
Corrective Action:				Date:	
Type: Flow Line	# 3				
Comment:	4" line from wellhead to separator. 1" line from separator to prime mover. 1" line from separator to heated tank.				
Corrective Action:				Date:	
Type: Bradenhead	# 1				
Comment:	PVC access				
Corrective Action:				Date:	
Type: Pump Jack	# 1				
Comment:					
Corrective Action:				Date:	
Type: Gas Meter Run	# 1				
Comment:	4" line from separator to meterhouse. Calibration date 7/25/2023.				
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 1				
Comment:					
Corrective Action:				Date:	
Type: Bird Protectors	# 2				
Comment:	On separator vent stack and heated tank vent stack.				
Corrective Action:				Date:	
Type: Prime Mover	# 1				
Comment:	Natural gas motor				
Corrective Action:				Date:	
Type: Deadman # & Marked	# 4				
Comment:					
Corrective Action:				Date:	
Type: Ancillary equipment	# 1				
Comment:	Telemetry with solar panel.				
Corrective Action:				Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
----------	---	----------	------	---------	--------	--

PRODUCED WATER	1	500 BBLs	HEATED STEEL AST		37.135670,-107.933640	
Comment:						
Corrective Action:						Date:
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities									
Facility ID:	258094	Type:	WELL	API Number:	067-08322	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	04/19/2023		Annual Brhd Completed?	Yes					
Last Brhd Test Results	Initial Surf Csg Pressure:	0		Fluid Type:					
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:				Date:					

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Ditches	Pass			
Berms	Pass	Culverts	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403531758	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6252658">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6252658</a>
712700662	Well Location Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6252645">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6252645</a>