

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/21/2023

Submitted Date:

09/22/2023

Document Number:

707800612

FIELD INSPECTION FORMLoc ID 335042 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	
, COGCC		shaun.kellerby@state.co.us	

General Comment:**CECMC Inspection Report Summary**

On Thursday 9/21/2023, I, Inspector Scott Ramsey and supervisor Shaun Kelerby, conducted a FLIRR inspection at approximate Lat/Long 39.41133763, -108.0722823 and 39.409922, -108.073693. TEP SG 41-26 pad, Location # 335042 is the closest location to the coordinates.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed active venting from the ground at 39.409922,

-108.073693. Shaun contacted TEP at 1400 and they responded immediately. They were on site at 1430. They believe the pipeline is Williams. TEP has contacted them and are in route.

I did not do a full inspection of location SG 41-26, but did have to go to location to get emergency number. Therefore there is a corrective action for this inspection.

During this inspection the following compliance issues were observed:

1. No signage at entrance of location

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

LocationOverall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	No signage at entrance of location		
Corrective Action:	Provide proper signage	Date:	09/29/2023

Emergency Contact Number:

Comment:	911/970-285-9377		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Optical Gas Imaging SurveySurvey Type: ComplaintCurrent Operations: ☐ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: _____ Long: _____

Wind: Gusts Speed: _____ (mph) Direction From: SW Weather: Clear Temperature: 82 (F)Assisting Staff Shaun Kellerby Camera #: 1☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
1:38	PM	1:52	PM	Pipeline

Comment: Inspection due to aircraft partner from CDPHE. While there, I observed active venting from the ground at 39.409922.-108.073693. Shaun contacted TEP at 1400 and they responded immediately. They were on site at 1430. They believe the pipeline is Williams. TEP has contacted Williams midstream and are in route.

Corrective Action: _____ Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707800613	OGI Video	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6261024
707800614	OGI Video	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6261025
707800615	Photo of area leak detected	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6261026