

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUBERG RWF 33-23 Pad

Location ID: 383326



Photo # 144 From entrance to location



Photo # 145 From entrance to location

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUNBERG RWF 33-23 Pad

Location ID: 383326



Photo # 146 Location

Photo # 147 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUNBERG RWF 33-23 Pad

Location ID: 383326



Photo # 148 Location



Photo # 149 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUNBERG RWF 33-23 Pad

Location ID: 383326



Photo # 150 Location



Photo # 151 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUNBERG RWF 33-23 Pad

Location ID: 383326



Photo # 152 Location



Photo # 163 PRV has plastic in relief port & no vent line

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUNBERG RWF 33-23 Pad

Location ID: 383326



Photo # 164 PRV has plastic in relief port & no vent line



Photo # 169 Stained soils & gravel

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUNBERG RWF 33-23 Pad

Location ID: 383326



Photo # 170 Stained soils & gravel



Photo # 171 Stained soils & gravel

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUNBERG RWF 33-23 Pad

Location ID: 383326



Photo # 172 Stained soils & gravel



Photo # 174 Stained soils & gravel

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUNBERG RWF 33-23 Pad

Location ID: 383326



Photo # 176 Stained soils & gravel



Photo # 177 Stained soils & gravel

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUNBERG RWF 33-23 Pad

Location ID: 383326



Photo # 178 Stained soils & gravel



Photo # 182 Stained soils & gravel