

Inspection Photos

Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad

Location ID: 323783



Photo # 265 From entrance to location



Photo # 266 Location

Inspection Photos

Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad

Location ID: 323783



Photo # 267 Location



Photo # 268 Location

Inspection Photos

Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad

Location ID: 323783



Photo # 269 Location



Photo # 270 Location

Inspection Photos

Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad

Location ID: 323783



Photo # 271 Location



Photo # 272 Location

Inspection Photos

Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad

Location ID: 323783



Photo # 276 Tank not properly labeled/missing required information



Photo # 277 Tank not properly labeled/missing required information

Inspection Photos

Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad

Location ID: 323783



Photo # 273 Stained gravel



Photo # 400 Stained soils & gravel



Inspection Photos

Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad

Location ID: 323783



Photo # 401 Stained soils & gravel



Photo # 404 Stained soils & gravel

Inspection Photos

Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad

Location ID: 323783



Photo # 405 Stained soils & gravel



Photo # 406 Stained soils & gravel

Inspection Photos

Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad

Location ID: 323783



Photo # 410 Stained soils & gravel



Photo # 411 Stained soils & gravel

Inspection Photos

Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad

Location ID: 323783




Photo # 412 Stained soils & gravel



Photo # 414 Stained soils & gravel

Inspection Photos

Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad

Location ID: 323783



Photo # 415 Stained soils & gravel



Photo # 284 Debris