

Storm Water Management and Erosion control

Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad

Location ID: 323783



Location Overview: Location is within High Priority/Density/Black Bear Habitat areas/Bald Eagle Roost site & in close proximity to NSO Habitat area. Location is approximately 240 yards from Beaver Creek & approximately 575 yards from the Colorado River.

Section/Township/Range: 23 6S94W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad
Location ID: 323783



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad
Location ID: 323783



Photo # 289 Erosion & transport of sediment off location & into a vegetated area (W/NW area of location)



Photo # 292 Erosion & transport of sediment off location & into a vegetated area (W/NW area of location)

Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad
Location ID: 323783



Photo # 294 Erosion & transport of sediment off location & into a vegetated area (W/NW area of location)



Photo # 312 Erosion & transport of sediment

Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad
Location ID: 323783



Photo # 314 Erosion & transport of sediment off location & into a vegetated area (W/NW area of location)



Photo # 317 Erosion & transport of sediment off location & into a vegetated area (W/NW area of location)

Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad
Location ID: 323783



Photo # 320 Erosion & transport of sediment off location & into a vegetated area (NW corner of location)



Photo # 332 Erosion & transport of sediment off location & into a vegetated area (NW corner of location)

Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad
Location ID: 323783



Photo # 333 Erosion & transport of sediment off location & into a vegetated area (NW corner of location)



Photo # 335 Erosion & transport of sediment off location & into a vegetated area (NW corner of location)

Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad
Location ID: 323783



Photo # 337 Erosion & transport of sediment off location & into a vegetated area



Photo # 338 Erosion & transport of sediment off location & into a vegetated area

Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad
Location ID: 323783



Photo # 339 Erosion & transport of sediment off location & into a vegetated area



Photo # 340 Erosion & transport of sediment off location & into a vegetated area

Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad
Location ID: 323783



Photo # 343 Erosion & transport of sediment off location & into a vegetated area



Photo # 346 Erosion & transport of sediment off location & into a vegetated area

Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad
Location ID: 323783



Photo # 341 Erosion & transport of sediment off location & into a vegetated area



Photo # 342 Erosion & transport of sediment off location & into a vegetated area

Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad
Location ID: 323783



**Photo # 348 Lack of stabilization & erosion on slope
/transport of sediment onto location/insufficient BMP's**



**Photo # 349 Lack of stabilization & erosion on slope
/transport of sediment onto location/insufficient BMP's**

Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad
Location ID: 323783



**Photo # 352 Erosion & transport of sediment onto location/
insufficient BMP's**



**Photo # 355 Erosion & transport of sediment onto location/
insufficient BMP's**

Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad
Location ID: 323783



**Photo # 356 Erosion & transport of sediment onto location/
insufficient BMP's**



**Photo # 363 Erosion & transport of sediment onto location/
insufficient BMP's**

Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad
Location ID: 323783



**Photo # 364 Erosion & transport of sediment onto location/
insufficient BMP's**



**Photo # 365 Erosion & transport of sediment onto location/
insufficient BMP's**

Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad
Location ID: 323783



**Photo # 373 Lack of stabilization & erosion on slope
/transport of sediment onto location/insufficient BMP's**



**Photo # 375 Lack of stabilization & erosion on slope
/transport of sediment onto location/insufficient BMP's**

Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad
Location ID: 323783



**Photo # 386 Erosion & transport of sediment onto location/
insufficient BMP's**



**Photo # 388 Erosion & transport of sediment onto location/
insufficient BMP's**

Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad
Location ID: 323783



**Photo # 389 Erosion & transport of sediment onto location/
insufficient BMP's**



**Photo # 392 Erosion & transport of sediment onto location/
insufficient BMP's**

Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad
Location ID: 323783



**Photo # 393 Erosion & transport of sediment onto location/
insufficient BMP's**



**Photo # 394 Erosion & transport of sediment onto location/
insufficient BMP's**

Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad
Location ID: 323783



**Photo # 395 Erosion & transport of sediment onto location/
insufficient BMP's**



**Photo # 378 Lack of stabilization & erosion on slope
/transport of sediment onto location/insufficient BMP's**