

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/22/2023

Submitted Date:

09/24/2023

Document Number:

708901771

**FIELD INSPECTION FORM**Loc ID 323783 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10550

Name of Operator: MUSTANG RESOURCES LLC

Address: 1660 LINCOLN STREET SUITE 1450

City: DENVER State: CO Zip: 80264

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

24 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Mustang		nwelch@vaqueroenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210798	WELL	PR	12/01/2016	GW	045-06556	MEAD 23-44-6S-94W	PR

**General Comment:****CECMC Inspection Report Summary**On 09/22/2023 at approximately 11:15 hours, I, Compliance Specialist, Wayne Smelser  
Conducted an on-site inspection at MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad.

Location # 323783 in Garfield County Colorado.

Location is within High Priority/Density/Black Bear Habitat areas/Bald Eagle Roost site &amp; in close proximity to NSO Habitat area.

Location is approximately 240 yards from Beaver Creek &amp; approximately 575 yards from the Colorado River.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Signs/Marker - Compressor engine oil tank not properly labeled/missing required information with a CA date of 10/24/2023.
2. Stormwater - Erosion & transport of sediment onto location, erosion & transport of sediment off location & lack of stabilization on slope with a CA date of 10/09/2023
3. Housekeeping - Stained soils & gravel in multiple areas of location with a CA date of 10/04/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator unit includes attached storage tank. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Compressor engine oil tank missing required information		
Corrective Action:	All Tanks with a capacity of 10 Barrels or greater will be labeled or posted with the following information:  A. Name of Operator; B. Operator's emergency contact telephone number; C. Tank capacity; D. Tank contents; and E. NFPA label or equivalent globally harmonized label.		Date: 10/24/2023
Type	CONTAINERS		
Comment:	Compressor engine oil tank		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	911/888-291-8588		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Debris - please refer to photo log		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Stained soils & gravel in multiple areas of location		
Corrective Action:	Remove and properly dispose of all stained soils and gravel.		Date: 10/04/2023
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type LOCATION

Comment: Barbed wire

Corrective Action:

Date:

**Equipment:**

corrective date

Type: Horizontal Heated Separator

# 1

Comment:

Corrective Action:

Date:

Type: Bradenhead

# 1

Comment: No form of pressure monitoring equipment located on bradenhead, bradenhead valve is accessible.

Corrective Action:

Date:

Type: Plunger Lift

# 0

Comment: Well is not on plunger lift

Corrective Action:

Date:

Type: Ancillary equipment

# 1

Comment: Compressor engine oil tank

Corrective Action:

Date:

Type: Bird Protectors

# 2

Comment:

Corrective Action:

Date:

Type: Compressor

# 1

Comment:

Corrective Action:

Date:

Type: Deadman # &amp; Marked

# 4

Comment: Marked

Corrective Action:

Date:

Type: Gas Meter Run

# 2

Comment:

Corrective Action:

Date:

**Tanks and Berms:**

Contents

#

Capacity

Type

Tank ID

SE GPS

OTHER

1

&lt;50 BBLS

STEEL AST

,

Comment: Separate containment

Corrective Action:

Date:

**Paint**

Condition Adequate

Inspector Name: Smelser, Wayne

Other (Content)	Compressor engine oil	
Other (Capacity)	500 gal	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent		
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	300 BBLS	STEEL AST		,	
Comment:	Separate containment					
Corrective Action:						Date:

**Paint**

Condition	Adequate	
-----------	----------	--

Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent		
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	210798	Type:	WELL	API Number:	045-06556	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well not on plunger lift								
Corrective Action:				Date:					

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Fail					Erosion & transport of sediment off location
		Gravel				Sparse
Other	Fail					Lack of stabilization on slope
Gravel						Sparse in areas
Other	Fail					Erosion & transport of sediment onto location
		Compaction				Some light compaction
Compaction						Areas with light compaction

Comment: 1. Erosion & transport of sediment onto location/insufficient BMP's  
 2. Erosion & transport of sediment off location & into vegetation/insufficient BMP's  
 3. Lack of stabilization on slope & transport of sediment onto location/insufficient BMP's

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved.

Date: 10/09/2023

Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Please refer to Signs/Marker, Housekeeping & Stormwater for observed compliance issues.	smelserw	09/24/2023

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708901773	Inspection 708901771 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6262158">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6262158</a>
708901774	Inspection 708901771 Stormwater photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6262161">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6262161</a>