

Comment: Metal signs posted on wellhead/pumpjack fenced enclosure. The ANIMAS 34-10 36-1 is not signed.

Corrective Action: Moved fenced enclosure back around Animas 34-10 36-1 to satisfy the signage and unused equipment (pipe fence) section of the INC.



Comment: Disconnected chemical container positioned approximately 10 feet from wellhead at the ANIMAS 34-10 36-2A. See Photos #4 & #5. Muffler hose and manifold parts on ground beside prime mover at the ANIMAS 34-10 36-2A. See Photo #3.

Corrective Action: Removed chemical trailer and reconnected muffler on Animas 34-10 #36-2A to satisfy unused equipment section of the INC.





Comment: Sections of pipe rail fencing placed along the edge of the location. See Photos #6 & #7.

Corrective Action: Moved fenced enclosure back around Animas 34-10 36-1 to satisfy the signage and unused equipment (pipe fence) section of the INC.





Comment: Lube oil container not in spill prevention at the 2A wellhead.

Corrective Action: Installed Spill containment to satisfy that section of the INC.



Comment: Several guy anchors unmarked or marker is broken on the ground.

Corrective Action: Installed Markers on the rig anchors across all 3 locations to satisfy that part of the INC.





