

WELL NAME: HILL RANCH 36-11, API #: 071-09531, INSP. # 695108675



PHOTO 1: WELL SIGN






**PHOTO 2: LOCATION**







**PHOTO 3: WELLHEAD AND EQUIPMENT**







**PHOTO 4: QUICK CONNECTIONS ON DYDRO HOSES ARE LEAKING. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. CA DATE 9-30-2023.**







**PHOTO 5: AREA OF IMPACTED SOIL UNDER DYDRO QUICK CONNECT HOSED. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. CA DATE 9-30-2023.**







**PHOTO 6: RUST COLORED IMPACTED SOIL APPEARS TO BE FROM ROD PACKING LEAKING OVER MULTIPLE EVENTS. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. CA DATE 9-30-2023.**

