

Inspection Photos

Location Name: MUSTANG RESOURCES LLC YOUNBERG 23-24-6S-94W Pad

Location ID: 323785



Photo # 120 From entrance to location



Photo # 121 Location

Inspection Photos

Location Name: MUSTANG RESOURCES LLC YOUNBERG 23-24-6S-94W Pad

Location ID: 323785



Photo # 122 Location

Photo # 123 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: MUSTANG RESOURCES LLC YOUNBERG 23-24-6S-94W Pad

Location ID: 323785



Photo # 124 Unregistered domestic tap

Photo # 125 Unregistered domestic tap

Inspection Photos

Location Name: MUSTANG RESOURCES LLC YOUNBERG 23-24-6S-94W Pad

Location ID: 323785



Photo # 126 PRV lacks vent line



Photo # 127 PRV lacks vent line