

Inspection Photos

Location Name: MUSTANG RESOURCES LLC LOUTHAN 34-32-6S-94W Pad

Location ID: 323819



Photo # 639 From entrance to location



Photo # 640 Location

Inspection Photos

Location Name: MUSTANG RESOURCES LLC LOUTHAN 34-32-6S-94W Pad

Location ID: 323819



Photo # 641 Location



Photo # 642 Improperly marked deadman

Inspection Photos

Location Name: MUSTANG RESOURCES LLC LOUTHAN 34-32-6S-94W Pad

Location ID: 323819



Photo # 643 Unmarked deadman



Photo # 644 Debris

Inspection Photos

Location Name: MUSTANG RESOURCES LLC LOUTHAN 34-32-6S-94W Pad

Location ID: 323819



Photo # 641 No signage at wellhead