

HILL RANCH 36-10-67 (HILL RANCH 36-11) API# 05-071-09533 – OGRIS OPERATING  
COGCC OPERATOR NUMBER 10758 - DATE: SEPTEMBER 27, 2023  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT #695108675



PHOTO 1: THE HYDRAULIC LEAK WAS REPAIRED AND EQUIPMENT MAINTENANCE HAS BEEN PERFORMED. ALL IMPACTED SOIL WAS REMOVED FROM THE LOCATION AND FRESH PAD MATERIAL ADDED AROUND THE WELLHEAD. THE SELF INSPECTION PROCESS HAS BEEN REVIEWED.

*NOTE: THE INSPECTION REPORTS THIS CORRECTIVE ACTION TO BE AT HILL RANCH 36-11 BUT UPON INVESTIGATION, THE LEAKING HYDRAULIC HOSES AND SOIL STAINS WERE DISCOVERED AT HILL RANCH 36-10-67.*