

Storm Water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 121-27 Pad

Location ID: 324140



Location Overview: Location is within High Priority/Density/Black Bear Habitat areas/Bald Eagle Roost site & in close proximity to NSO habitat area. Location is approximately 60 yards from the Colorado River & approximately 174 yards from Beaver Creek.

Section/Township/Range: 27 6S94W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 121-27 Pad
Location ID: 324140



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 121-27 Pad
Location ID: 324140



Photo # 768 Erosion on slope & transport of sediment off location/insufficient BMP's (S/SE area of location)



Photo # 769 Erosion on slope & transport of sediment off location/insufficient BMP's (S/SE area of location)

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 121-27 Pad
Location ID: 324140



Photo # 770 Erosion on slope & transport of sediment off location/insufficient BMP's (S/SE area of location)



Photo # 771 Erosion on slope & transport of sediment off location/insufficient BMP's (S/SE area of location)

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 121-27 Pad
Location ID: 324140



Photo # 772 Erosion on slope & transport of sediment off location/insufficient BMP's (S/SE area of location)



Photo # 773 Erosion on slope & transport of sediment off location/insufficient BMP's (S/SE area of location)

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 121-27 Pad
Location ID: 324140



Photo # 774 Erosion on slope & transport of sediment off location/insufficient BMP's (S/SE area of location)



Photo # 775 Erosion on slope & transport of sediment off location/insufficient BMP's (S/SE area of location)

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 121-27 Pad
Location ID: 324140



Photo # 776 Erosion on slope & transport of sediment off location/insufficient BMP's (S/SE area of location)



Photo # 777 Erosion on slope & transport of sediment off location/insufficient BMP's (S/SE area of location)

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 121-27 Pad
Location ID: 324140



Photo # 778 Erosion & transport of sediment off lease road (on short portion of lease road between production equipment & wellheads, near culvert)



Photo # 779 Erosion & transport of sediment off lease road (on short portion of lease road between production equipment & wellheads, near culvert)

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 121-27 Pad
Location ID: 324140



Photo # 780 Erosion & transport of sediment off lease road (on short portion of lease road between production equipment & wellheads, near culvert)



Photo # 781 Erosion & transport of sediment off lease road (on short portion of lease road between production equipment & wellheads, near culvert)

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 121-27 Pad
Location ID: 324140



**Photo # 782 Lack of stabilization/compaction on location
/insufficient BMP's**



**Photo # 783 Lack of stabilization/compaction on location
/insufficient BMP's**

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 121-27 Pad
Location ID: 324140



**Photo # 784 Lack of stabilization/compaction on location
/insufficient BMP's**



**Photo # 785 Lack of stabilization/compaction on location
/insufficient BMP's**

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 121-27 Pad
Location ID: 324140



**Photo # 786 Lack of stabilization/compaction on location
/insufficient BMP's**



**Photo # 787 Lack of stabilization/compaction on location
/insufficient BMP's**

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 121-27 Pad
Location ID: 324140



**Photo # 788 Lack of stabilization/compaction on location
/insufficient BMP's**



**Photo # 789 Lack of stabilization/compaction on location
/insufficient BMP's**

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 121-27 Pad
Location ID: 324140



**Photo # 790 Lack of stabilization/compaction on lease road
/insufficient BMP's**



**Photo # 791 Lack of stabilization/compaction on lease road
/insufficient BMP's**

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 121-27 Pad
Location ID: 324140



**Photo # 792 Lack of stabilization/compaction on lease road
/insufficient BMP's**



**Photo # 793 Lack of stabilization/compaction on location
/insufficient BMP's**

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 121-27 Pad
Location ID: 324140



**Photo # 794 Lack of stabilization/compaction on location
/insufficient BMP's**



**Photo # 795 Lack of stabilization/compaction on location
/insufficient BMP's**

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 121-27 Pad
Location ID: 324140



Photo # 796 Vehicle tracks traveling off the working pad area into the interim area



Photo # 797 Vehicle tracks traveling off the working pad area into the interim area

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 121-27 Pad
Location ID: 324140



**Photo # 798 Lack of stabilization/compaction on location
/insufficient BMP's**



**Photo # 799 Lack of stabilization/compaction on location
/insufficient BMP's**

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 121-27 Pad
Location ID: 324140



**Photo # 800 Lack of stabilization/compaction on location
/insufficient BMP's**



**Photo # 801 Lack of stabilization/compaction on location
/insufficient BMP's**