

## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 11-15A (RJ11) Pad

Location #: 324423



**Photo # 1031 From entrance to location**



**Photo # 1032 From entrance to location**

# Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 11-15A (RJ11) Pad

Location #: 324423



Photo # 1033 Location

Photo # 1034 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 11-15A (RJ11) Pad

Location #: 324423



Photo # 1035 Location



Photo # 1036 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 11-15A (RJ11) Pad

Location #: 324423



Photo # 1037 Location



Photo # 1038 Cellar lacks wildlife egress

## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 11-15A (RJ11) Pad

Location #: 324423



**Photo # 1039 Leaking valve on production tank/stained gravel**



**Photo # 1040 Fluid leaking from valve**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 11-15A (RJ11) Pad

Location #: 324423



**Photo # 1041 Fluid leaking from valve**



**Photo # 1042 Fluid leaking from valve**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 11-15A (RJ11) Pad

Location #: 324423



**Photo # 1043 Leaking valve on production tank/stained gravel**



**Photo # 1044 Stained gravel**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 11-15A (RJ11) Pad

Location #: 324423



Photo # 1045 Stained gravel



Photo # 1046 Stained gravel

## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 11-15A (RJ11) Pad

Location #: 324423



**Photo # 1047 Stained gravel**