

Inspection Photos

Location Name: CAERUS PICEANCE LLC SCARBER RO2 Pad

Location #: 334669



Photo # 963 From entrance to location



Photo # 964 From entrance to location

Inspection Photos
Location Name: CAERUS PICEANCE LLC SCARBER RO2 Pad
Location #: 334669




Photo # 965 Location

Photo # 966 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC SCARBER RO2 Pad

Location #: 334669



Photo # 967 Location



Photo # 968 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC SCARBER RO2 Pad

Location #: 334669



Photo # 969 Location



Photo # 970 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC SCARBER RO2 Pad

Location #: 334669



Photo # 971 Debris

Photo # 972 Debris

Inspection Photos

Location Name: CAERUS PICEANCE LLC SCARBER RO2 Pad

Location #: 334669



Photo # 973 Debris



Photo # 974 Open ended load line

Inspection Photos

Location Name: CAERUS PICEANCE LLC SCARBER RO2 Pad

Location #: 334669



Photo # 975 Open ended load line



Photo # 976 Open ended load line

Inspection Photos

Location Name: CAERUS PICEANCE LLC SCARBER RO2 Pad

Location #: 334669



Photo # 977 Flowline heating insulation with a hole/wildlife hazard