

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/22/2023

Submitted Date:

09/25/2023

Document Number:

708901775

FIELD INSPECTION FORMLoc ID 323785 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10550

Name of Operator: MUSTANG RESOURCES LLC

Address: 1660 LINCOLN STREET SUITE 1450

City: DENVER State: CO Zip: 80264

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

16 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Mustang		nwelch@vaqueroenergy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210803	WELL	PR	01/01/2018	GW	045-06561	YOUBERG 23-24-6S-94W	PR

General Comment:**CECMC Inspection Report Summary**

On 09/22/2023 at approximately 09:40 hours, I, Compliance Specialist, Wayne Smelser
 Conducted an on-site inspection at MUSTANG RESOURCES LLC YOUBERG 23-24-6S-94W Pad.
 Location # 323785 in Garfield County Colorado.
 Location is within High Priority/Density/Black Bear/NSO Habitat areas & Bald Eagle Roost site.
 Location is approximately 104 yards from Beaver Creek.
 While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Flowline - Domestic tap appears to be connected and in operation, no form 44 on file with a CA date of 10/25/2023
2. Equipment - Meter calibration info not conspicuously posted with a CA date of 10/05/2023
3. Equipment - PRV on domestic tap lacks vent line with a CA date of 10/02/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.
 This is a summary of inspection report.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Type	BATTERY			
Comment:	No tank battery			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911/888-291-8588			
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	LOCATION			
Comment:	Barbed wire			
Corrective Action:				Date:
Equipment:				
Type: Gas Meter Run			# 1	corrective date
Comment:	Meter calibration info not conspicuously posted			
Corrective Action:	The Operator will conspicuously post and maintain the date of the last meter calibration in a legible condition at each meter at all times.			Date: 10/05/2023
Type: Other	# 1			
Comment:	PRV on domestic tap lacks vent line			
Corrective Action:	Operators are responsible for ensuring that operations are conducted with due regard for the safety of employees, for the preservation and conservation of property, and for protecting and minimizing adverse impacts to public health, safety, welfare, the environment, and wildlife resources.			Date: 10/02/2023
Type: Deadman # & Marked	# 1			
Comment:	Marked			
Corrective Action:				Date:
Type: Plunger Lift	# 0			

Comment:	Well not on plunger lift		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	No form of pressure monitoring equipment located on bradenhead, bradenhead valve is accessible.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 210803 Type: WELL API Number: 045-06561 Status: PR Insp. Status: PR**Producing Well**Comment: Producing, well not on plunger lift

Corrective Action:

Date:

Flowline

#1 Type: Non-Well Site

of Lines

Flowline DescriptionFlowline Type: Non-Well Site

Size:

Material:

Variance:

Age:

Contents:

Integrity Summary

Failures:

Spills:

Repairs Made:

Coatings:

H2S:

Cathodic Protection:

Pressure Testing

Witnessed:

Test Result:

Charted:

COGCC Rules(check all that apply)☐ 1101. Installation and Reclamation☐ 1102. Operations, Maintenance, and Repair☐ 1103. AbandonmentComment: Domestic tap appears to be connected and in operation, no form 44 on file.Corrective Action: Submit an eForm 44 Flowline ReportDate: 10/25/2023

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				Sparse
Compaction						Light compaction in some areas
Gravel						Sparse to none in some areas
		Compaction				

Comment: Location appears to have some gravel throughout the location with light compaction. Places with sparse to no gravel are present on location. Sparse gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Please refer to Equipment & Flowline for observed compliance issues.	smelserw	09/25/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403540780	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6263574
708901776	Inspection 708901775 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6263570
708901777	Inspection 708901775 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6263571