

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/25/2023

Submitted Date:

09/25/2023

Document Number:

708901781

**FIELD INSPECTION FORM**Loc ID 323819 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10550

Name of Operator: MUSTANG RESOURCES LLC

Address: 1660 LINCOLN STREET SUITE 1450

City: DENVER State: CO Zip: 80264

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

14 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Mustang		nwelch@vaqueroenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210876	WELL	PR	03/01/2022	GW	045-06634	LOUTHAN 34-32-6S-94W	PR

**General Comment:****CECMC Inspection Report Summary**

On 09/25/2023 at approximately 11:32 hours, I, Compliance Specialist, Wayne Smelser

Conducted an on-site inspection at MUSTANG RESOURCES LLC LOUTHAN 34-32-6S-94W Pad.

Location # 323819 in Garfield County Colorado.

Location is within High Priority/Density/Black Bear Habitat areas &amp; in close proximity to NSO Habitat area.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Signs/Marker - No signage at wellhead with a CA date of 10/25/2023

2. Equipment - Unmarked deadman with a CA date of 10/09/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	BATTERY			
Comment:	No tank battery			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	No signage at wellhead			
Corrective Action:	A permanent sign will be conspicuously located at the wellhead and will identify: A. The Well name; B. The API number; C. Its legal location, including the quarter/quarter section. D. Name of the Operator; E. Telephone number at which the Operator can be reached at all times; F. Telephone number for local emergency services (911 where available); and G. The public road used to access the Well.			Date: 10/25/2023
Emergency Contact Number:				
Comment:	911/1-888-291-8588			
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	DEBRIS			
Comment:	Debris - please refer to photo log			
Corrective Action:				Date:
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No _____				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	WELLHEAD			
Comment:	Barbed wire			
Corrective Action:				Date:
Type	LOCATION			
Comment:	Barbed wire fence			
Corrective Action:				Date:
<b>Equipment:</b>				
				corrective date
Type: Deadman # & Marked	# 4			

Comment:	2 marked deadman 1 improperly marked deadman 1 unmarked deadman			
Corrective Action:	All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor.		Date:	10/09/2023
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:			Date:	
Type: Bradenhead	# 1			
Comment:	No form of pressure monitoring equipment located on bradenhead, bradenhead valve is accessible.			
Corrective Action:			Date:	
Type: Plunger Lift	# 0			
Comment:	Well is not on plunger lift			
Corrective Action:			Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	210876	Type:	WELL	API Number:	045-06634	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well not on plunger lift								
Corrective Action:				Date:					

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
Compaction						
Gravel						Sparse to none
		Gravel				Sparse

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Please refer to Signs/Marker & Equipment for observed compliance issues.	smelserw	09/25/2023

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403540877	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6263615">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6263615</a>
708901782	Inspection 708901781 Stormwater photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6263611">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6263611</a>
708901783	Inspection 708901781 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6263612">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6263612</a>