

Inspection Photos
Location Name: Loehr Larry R 1
Location ID: 322864



Photo 1 well head and equipment



Photo 2 well head and equipment

Inspection Photos
Location Name: Loehr Larry R 1
Location ID: 322864



Photo 3 pumping unit



Photo 4 electrical panel

Inspection Photos
Location Name: Loehr Larry R 1
Location ID: 322864



Photo 5 stained soil around well head



Photo 6 unused equipment

Inspection Photos
Location Name: Loehr Larry R 1
Location ID: 322864




Photo 7 access road