

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/24/2023

Submitted Date:

10/03/2023

Document Number:

709100115

**FIELD INSPECTION FORM**

Loc ID: 450327      Inspector Name: Heibel, Krystal      On-Site Inspection:       2A Doc Num: \_\_\_\_\_

**Status Summary:**

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

9 Number of Comments

5 Number of Corrective Actions

Corrective Action Response Requested

**Operator Information:**

OGCC Operator Number: 7800

Name of Operator: BEREN CORPORATION

Address: 2020 N BRAMBLEWOOD STREET

City: WICHITA      State: KS      Zip: 67206

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Wreath, Dana	(316) 265-3311X6720	dwreath@berexco.com	DESIGNATED AGENT
Reynolds, Rodney	316-337-8340	reynoldsr@berexco.com	All Inspections
Kay, Michael	316-249-7597	kaym@berexco.com	All Inspections
Krystal Heibel	303-817-5217	krystal.heibel@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
433738	TANK BATTERY	AC	07/26/2013		-	Brewer A Tank Battery 433738	EI

**General Comment:**

This is an environmental inspection of the Brewer "A" pit (Location ID 450327) and the Brewer A Tank Battery (Location ID 450327). Personell onsite around the former Brewer "A" Pit (Facility ID 111970) location at time of inspection.

ECMC inspector Krystal Heibel arrived onsite on September 26, 2023, around 11:30 AM to perform an Environmental Inspection. The work site is in close proximity to the Sterling Canal waterway.

Two Remediation Projects are active at this time:  
 Rem# 8567: Decommissioning the Brewer 'A' Pit (Facility ID 111967); hydrocarbon impacted soils identified  
 Rem# 10290: Decommissioning the Brewer "A" Pit (Facility ID 111968) closed in 9/23/1999  
 Rem# 10181: Remediation of impacted Groundwater

This location has had 4 pits on location:  
 Brewer "A" Pit (Facility ID 111970) closed in 9/23/1999  
 Brewer "A" Pit (Facility ID 111968) closed in 9/23/1999  
 Brewer "A" Pit (Facility ID 111967) closed in 10/6/2014  
 Brewer "A" Pit (Facility ID 111970) active

Any corrective actions from previous forms that have not been addressed are still applicable. Photos are attached to document site conditions at the time of the inspection.

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	11/03/2023

**Emergency Contact Number:**

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>

**Good Housekeeping:**

Type	TRASH		
Comment:	Trash observed on location.		
Corrective Action:	Comply with Rule 606	Date:	10/11/2023
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment on site.		
Corrective Action:	Comply with Rule 606	Date:	10/11/2023

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:	Large burrows observed underneath the tanks.				
Corrective Action:	Inspect, maintain and repair tanks to comply with rule 609.b.				Date: 11/03/2023

**Paint**

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Inadequate berms around tank(s). Large burrows observed.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 912.d.(1).			Date: 10/24/2023

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 433738 Type: TANK API Number: - Status: AC Insp. Status: EI

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
709100116	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6272410">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6272410</a>