


Storm Water Management and Erosion control
Location Name: CAERUS PICEANCE LLC F24W Pad
Location #: 334693



**Location Overview: Location is within High
Priority/Density/Black Bear Habitat areas & in close proximity
to NSO Habitat area. Location is approximately 349 yards
from West Mamm Creek.**

Section/Township/Range: 24 7S93W



Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC F24W Pad
Location #: 334693



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC F24W Pad
Location #: 334693



Photo # 1358 Lack of stabilization/compaction/insufficient BMP's



Photo # 1359 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC F24W Pad
Location #: 334693



Photo # 1360 Lack of stabilization/compaction/insufficient BMP's



Photo # 1361 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC F24W Pad
Location #: 334693



Photo # 1362 Lack of stabilization/compaction/insufficient BMP's



Photo # 1363 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC F24W Pad
Location #: 334693



Photo # 1364 Lack of stabilization/compaction/insufficient BMP's



Photo # 1365 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC F24W Pad
Location #: 334693



Photo # 1366 Lack of stabilization/compaction/insufficient BMP's



Photo # 1367 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC F24W Pad
Location #: 334693



Photo # 1368 Lack of stabilization/compaction/insufficient BMP's



Photo # 1369 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC F24W Pad
Location #: 334693



Photo # 1370 Lack of stabilization/compaction/insufficient BMP's



Photo # 1371 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC F24W Pad
Location #: 334693



Oct 3, 2023 at 12:09:57 PM
CO

Photo # 1372 Vehicle tracking onto lease road/insufficient tracking BMP's



Oct 3, 2023 at 12:08:10 PM
CO

Photo # 1373 Vehicle tracking onto lease road/insufficient tracking BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC F24W Pad
Location #: 334693



Photo # 1374 Vehicle tracking onto lease road/insufficient tracking BMP's



Photo # 1375 Vehicle tracking onto lease road/insufficient tracking BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC F24W Pad
Location #: 334693



Oct 3, 2023 at 12:04:57 PM
CO

Photo # 1376 Vehicle tracking onto lease road/insufficient tracking BMP's



Oct 3, 2023 at 12:05:05 PM
CO

Photo # 1377 Vehicle tracking onto lease road/insufficient tracking BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC F24W Pad
Location #: 334693



Photo # 1378 Vehicle tracking onto lease road/insufficient tracking BMP's



Photo # 1379 Vehicle tracking onto lease road/insufficient tracking BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC F24W Pad
Location #: 334693



Photo # 1380 Vehicle tracking onto lease road/insufficient tracking BMP's



Photo # 1381 Vehicle tracking onto lease road/insufficient tracking BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC F24W Pad
Location #: 334693



Photo # 1382 Vehicle tracking onto lease road/insufficient tracking BMP's



Photo # 1383 Vehicle tracking onto lease road/insufficient tracking BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC F24W Pad
Location #: 334693



Photo # 1384 Vehicle tracking onto lease road/insufficient tracking BMP's



Photo # 1385 Vehicle tracking onto lease road/insufficient tracking BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC F24W Pad
Location #: 334693



Photo # 1386 Vehicle tracking onto lease road/insufficient tracking BMP's



Photo # 1387 Vehicle tracking onto lease road/insufficient tracking BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC F24W Pad
Location #: 334693



Photo # 1388 Vehicle tracking onto lease road/insufficient tracking BMP's



Photo # 1389 Vehicle tracking onto lease road/insufficient tracking BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC F24W Pad
Location #: 334693



Photo # 1390 Vehicle tracking onto lease road/insufficient tracking BMP's



Photo # 1391 Vehicle tracking onto lease road/insufficient tracking BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC F24W Pad
Location #: 334693



Photo # 1392 Vehicle tracking onto lease road/insufficient tracking BMP's



Photo # 1393 Vehicle tracking onto lease road/insufficient tracking BMP's