

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/03/2023

Submitted Date:

10/04/2023

Document Number:

708901842

**FIELD INSPECTION FORM**Loc ID 334693 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

29 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	
Toews, Wesley		wtoews@blm.gov	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285600	WELL	PR	06/14/2010	GW	045-12525	COUEY 24-6 (F24W)	PR
285601	WELL	PR	09/01/2018	GW	045-12524	COUEY FEDERAL 24-3 (F24W)	PR
285602	WELL	PR	07/15/2007	GW	045-12523	COUEY FEDERAL 24-3D (F24W)	PR
293065	WELL	PR	02/01/2011	GW	045-14862	COUEY 24-7 (F24W)	PR
293066	WELL	PR	01/01/2011	GW	045-14863	COUEY 24-10B (F24W)	PR
293067	WELL	PR	09/21/2008	GW	045-14864	COUEY 24-10 (F24W)	PR
293068	WELL	PR	02/01/2011	GW	045-14865	COUEY 24-11 (F24W)	PR
293159	WELL	PR	02/01/2011	GW	045-14907	COUEY 24-2D (F24W)	PR
293394	WELL	SI	06/01/2023	GW	045-14954	COUEY 24-6D (F24W)	SI

**General Comment:**

CECMC Inspection Report Summary

On 10/03/2023 at approximately 11:47 hours, I, Compliance Specialist, Wayne Smelser

Conducted a follow up inspection at CAERUS PICEANCE LLC F24W Pad.

Location # 334693 in Garfield County Colorado.

Please refer to inspection 708901332 conducted on 08/08/2023, previous corrective action has been completed.

Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area.

Location is approximately 349 yards from West Mamm Creek.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Stormwater - Lack of stabilization/compaction on location & vehicle tracking onto lease road with a CA date of 10/19/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	911/970-285-2615	
Corrective Action:		Date: _____

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Debris - please refer to photo log		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
In Containment:	No			
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

**Fencing/:**

Type	LOCATION		
Comment:	Barbed wire		

Corrective Action:		Date:	
<b>Equipment:</b>		corrective date	
Type: Gas Meter Run	# 9		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 8		
Comment: All wells on plunger lift			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 8		
Comment: Pressure transducers located on all bradenhead, all bradenhead valves are accessible.			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment: Summit Midstream			
Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 9		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment: Chemical tanks			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment: Centralized containment					
Corrective Action:		Date:			

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	
Comment:				

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	4	300 BBLs	STEEL AST		,	
Comment: Centralized containment						
Corrective Action:					Date:	
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient			
Comment:						
Corrective Action:					Date:	
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities						
Facility ID:	285600	Type:	WELL	API Number: 045-12525	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
Facility ID:	285601	Type:	WELL	API Number: 045-12524	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
Facility ID:	285602	Type:	WELL	API Number: 045-12523	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
Facility ID:	293065	Type:	WELL	API Number: 045-14862	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
Facility ID:	293066	Type:	WELL	API Number: 045-14863	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
Facility ID:	293067	Type:	WELL	API Number: 045-14864	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
Facility ID:	293068	Type:	WELL	API Number: 045-14865	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
Facility ID:	293159	Type:	WELL	API Number: 045-14907	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:

Facility ID:	293394	Type:	WELL	API Number:	045-14954	Status:	SI	Insp. Status:	SI
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Idle Well

Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Culverts				
Check Dams						
				Material Handling And Spill Prevention		Chemical tank containments
Ditches						
				Vehicle Tracking	Fail	Tracking onto lease road
		Gravel				Sparse
		Compaction				Light compaction in some sections
Retention Ponds						
Compaction	Fail					Lack of stabilization/compaction
		Ditches				
Gravel						Sparse to none
Rip Rap						

Comment: 1. Lack of stabilization/compaction/insufficient BMP's

2. Vehicle tracking onto lease road/insufficient tracking BMP's

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved.

Date: 10/19/2023

Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Please refer to Stormwater for observed compliance issues.	smelserw	10/04/2023

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708901843	Inspection 708901842 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6273976">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6273976</a>
708901845	Inspection 708901842 Stormwater photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6273977">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6273977</a>