

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/25/2023

Submitted Date:

09/29/2023

Document Number:

708901807

FIELD INSPECTION FORM

Loc ID 335258 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10550

Name of Operator: MUSTANG RESOURCES LLC

Address: 1660 LINCOLN STREET SUITE 1450

City: DENVER State: CO Zip: 80264

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

13 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Mustang		nwelch@vaqueroenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210822	WELL	PR	03/01/2022	GW	045-06580	HAYNES-HARRIS 27-43-6S-94W	PR

General Comment:**CECMC Inspection Report Summary**

On 09/25/2023 at approximately 12:04 hours, I, Compliance Specialist, Wayne Smelser

Conducted an on-site inspection at MUSTANG RESOURCES LLC HAYNES-HARRIS 27-43-6S-94W Pad.

Location # 335258 in Garfield County Colorado.

Location is within High Priority/Density/NSO/Black Bear Habitat areas & Bald Eagle Nest/Roost sites.

Location is approximately 142 yards from Porcupine Creek & approximately 311 yards from the Colorado River.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Stormwater - Erosion & transport of sediment with a CA date of 10/14/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Type	BATTERY			
Comment:	No tank battery			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911/888-291-8588			
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Equipment:				
Type: Plunger Lift	# 0			corrective date
Comment:	Well is not on plunger lift			
Corrective Action:				Date:
Type: Bradenhead	# 1			
Comment:	No form of pressure monitoring equipment located on bradenhead, bradenhead valve is accessible.			
Corrective Action:				Date:
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:				Date:
Type: Deadman # & Marked	# 2			
Comment:	Marked			
Corrective Action:				Date:
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:				Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	210822	Type:	WELL	API Number:	045-06580	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well not on plunger lift								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Culverts						
Ditches						
Compaction						Areas of light compaction
		Compaction				
		Ditches				
		Gravel				Sparse in some areas
		Culverts				
Gravel						Sparse to none
Other	Fail					Erosion & transport of sediment

Comment: 1. Erosion & transport of sediment/insufficient BMP's

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved.

Date: 10/14/2023

Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Please refer to Stormwater for observed compliance issue.	smelserw	09/29/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403546621	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6269706
708901808	Inspection 708901807 Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6269695
708901809	Inspection 708901807 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6269696