

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/29/2023

Submitted Date:

09/29/2023

Document Number:

712700685

FIELD INSPECTION FORM

Loc ID 325931 Inspector Name: Pattillo, Curtis On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 21 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		sjninspections@ikavenergy.com	All SW Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215586	WELL	PR	09/01/2019	CBM	067-07191	THACKER 1	PR

General Comment:

SW Compliance Specialist Curtis Pattillo conducted a follow up field inspection to verify completion of corrective actions identified in FIR Document #702500317.

Location			
Lease Road:			
Type	Access		
comment:	Locked gate, 2C40 key.		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Metal sign posted at location entrance.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	NFPA placard on meterhouse.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Posted on wellhead sign.		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	Lube oil visible on wellhead piping, observed impacted material around wellhead.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002..(2).D.	Date:	10/07/2023
Type	STORAGE OF SUPL		
Comment:	Landowner has two trailers and a water truck parked on location.		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	SEPARATOR		
Comment:	Cattle panel enclosure around meterhouse and separator.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Cattle panel enclosure around pumpjack and wellhead.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Pipe rail enclosure around cathodic protection.		
Corrective Action:		Date:	

Type	OTHER		
Comment:	Cattle panel enclosure around telemetry.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gathering Line	# 1		
Comment:	Buried valve can.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry		
Corrective Action:		Date:	
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	2" line from separator to meterhouse. Calibration date 7/5/2023.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	PVC access		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	3" line from wellhead to separator.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electrical service panel, boxes.		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			

Comment:		
Corrective Action:	Date:	

--

Inspected Facilities

Facility ID: 215586 Type: WELL API Number: 067-07191 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 06/27/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Retention Ponds	Pass	Ditches	Pass			
Berms	Pass	Culverts	Pass			
Rip Rap	Pass	Check Dams	Pass			
Compaction	Pass	Rip Rap	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403546477	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6269577
712700690	Well Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6269566