

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/04/2023

Submitted Date:

10/05/2023

Document Number:

701007463

FIELD INSPECTION FORM

Loc ID 337641 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10699
Name of Operator: OWN RESOURCES OPERATING LLC
Address: 305 S RIDGE STREET #6279
City: BRECKENRIDGE State: CO Zip: 80424

Findings:

12 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Dolezal, Pat	(970) 332-3585	pat.dolezal@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287451	WELL	PR	01/01/2011	GW	125-10431	FIX 13-16	PR

General Comment:

[Routine Inspection](#)

Location

Lease Road:			
	Type Access		
	comment: Trail through farm ground		
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
	Type WELLHEAD		
	Comment: Lease sign by unit		
Corrective Action:			Date:
	Type BATTERY		
	Comment: Lease sign by water tank		
Corrective Action:			Date:
	Type TANK LABELS/PLACARDS		
	Comment: Metal sign by water tank		
Corrective Action:			Date:

Emergency Contact Number:			
	Comment:		
	Corrective Action:		Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
	Type PUMP JACK		
	Comment: Metal panels around unit and wellhead		
Corrective Action:			Date:

Equipment:			corrective date
Type: Pump Jack	# 1		
	Comment: Churchill unit		
Corrective Action:			Date:
Type: Prime Mover	# 1		
	Comment: Kohler gas engine		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
	Comment: Gas scrubber		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		39.969720,-102.317480
Comment: Fiberglass water tank 50% buried 275' west of wellhead by county road					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	210bbbs
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 287451 Type: WELL API Number: 125-10431 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Casing production. Central meter run for \(CDM Partnership 34-17, 33-17, 43-17, FIX 13-16\) 550' NW of wellhead](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			

Comment: [Location and access are farmed over](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT