

Inspection Photos
Location Name: CAERUS PICEANCE LLC M34NE Pad
Location #: 334987



Photo # 1910 From entrance to location



Photo # 1911 From entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC M34NE Pad

Location #: 334987



Photo # 1912 Location



Photo # 1913 Location



Inspection Photos
Location Name: CAERUS PICEANCE LLC M34NE Pad
Location #: 334987



Photo # 1914 Location



Photo # 1915 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC M34NE Pad
Location #: 334987



Photo # 1916 KELLY 34-13 well bradenhead connected to flowline



Photo # 1917 KELLY 34-13 well bradenhead connected to flowline

Inspection Photos
Location Name: CAERUS PICEANCE LLC M34NE Pad
Location #: 334987



Photo # 1918 Debris



Photo # 1919 Debris

Inspection Photos
Location Name: CAERUS PICEANCE LLC M34NE Pad
Location #: 334987



Photo # 1920 Debris



Photo # 1921 Debris

Inspection Photos
Location Name: CAERUS PICEANCE LLC M34NE Pad
Location #: 334987



Photo # 2272 From inspection 708900904 conducted on 06/30/2023 Hole in secondary containment liner/liner needs maintenance



Photo # 1922 Hole in secondary containment liner/liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC M34NE Pad
Location #: 334987



Photo # 2274 From inspection 708900904 conducted on 06/30/2023 Hole in secondary containment liner/liner needs maintenance



Photo # 1923 Hole in secondary containment liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC M34NE Pad

Location #: 334987



Photo # 2280 From inspection 708900904 conducted on 06/30/2023 Hole in secondary containment liner/liner needs maintenance



Photo # 1924 Hole in secondary containment liner/liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC M34NE Pad
Location #: 334987



Photo # 2282 From inspection 708900904 conducted on 06/30/2023 Hole in secondary containment liner/liner needs maintenance



Photo # 1925 Hole in secondary containment liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC M34NE Pad

Location #: 334987



Photo # 1926 Hole in secondary containment liner/liner needs maintenance



Photo # 1927 Hole in secondary containment liner/liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC M34NE Pad
Location #: 334987



**Photo # 1928 Hole in secondary containment liner/liner
needs maintenance**



Photo # 1929 Stained gravel

Inspection Photos
Location Name: CAERUS PICEANCE LLC M34NE Pad
Location #: 334987



Photo # 1930 Unused equipment



Photo # 1931 Unused equipment/ECD disconnected

Inspection Photos

Location Name: CAERUS PICEANCE LLC M34NE Pad

Location #: 334987



Photo # 1932 Unused equipment/ECD disconnected