

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/06/2023

Submitted Date:

10/08/2023

Document Number:

708901899

FIELD INSPECTION FORM

Loc ID: 334987 Inspector Name: Smelser, Wayne On-Site Inspection: 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
 28 Number of Comments
 3 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 10456
 Name of Operator: CAERUS PICEANCE LLC
 Address: 1001 17TH STREET #1600
 City: DENVER State: CO Zip: 80202

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerusoilandgas.com	
, Engineering		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272244	WELL	PR	10/28/2004	GW	045-10055	KELLY 34-14 (M34NE)	PR
272245	WELL	PR	10/31/2004	GW	045-10054	KELLY 34-13 (M34NE}	PR
272633	WELL	PR	10/12/2004	GW	045-10112	KELLY 34-11C (M34NE)	PR
272634	WELL	SI	08/01/2022	GW	045-10111	KELLY 34-12C (M34NE)	SI

General Comment:

[CECMC Inspection Report Summary](#)
 On 10/06/2023 at approximately 11:21 hours, I, Compliance Specialist, Wayne Smelser Conducted a follow up inspection at CAERUS PICEANCE LLC M34NE pad. Location # 334987 in Garfield County Colorado. Please refer to inspection 708900904 conducted on 06/30/2023, 4 of the 5 previous corrective actions have been completed. Corrective action for Secondary containment liner needs maintenance has not been completed & CA date remains 07/23/2023. Location is within High Priority/Density/Black Bear Habitat areas & within close proximity to NSO Habitat area. While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Housekeeping - Stained gravel in secondary containment with a CA date of 10/18/2023
2. Housekeeping - Unused equipment on location with a CA date of 11/07/2023
3. Tanks & Berms - Secondary containment liner needs maintenance with a CA date of 07/23/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.
 This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911/970-285-2615		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	Stained gravel in secondary containment.		
Corrective Action:	Remove and properly dispose of all stained soils and gravel.		Date: 10/18/2023
Type	DEBRIS		
Comment:	Debris - please refer to photo log		
Corrective Action:			Date:
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment on location		
Corrective Action:	The storage of equipment and supplies not necessary for use on location is prohibited.		Date: 11/07/2023

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No _____

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Cattle panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Cattle panels		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Summit Midstream - cattle panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Cattle panels		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbed wire		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Cattle panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 4		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 4		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment:	Marked		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Summit Midstream		
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:	Pressure monitoring equipment located on all bradenhead. All bradenhead valves are accessible. KELLY 34-13 well bradenhead connected to flowline.		
Corrective Action:		Date:	
Type: Emission Control Device	# 2		

Comment: ECD next to tank battery is disconnected & not in use.		Date:
Corrective Action:		Date:
Type: Vertical Heated Separator	# 4	
Comment:		Date:
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	HEATED STEEL AST		,
Comment: Centralized containment					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Inadequate	Walls Insufficient	Base Sufficient	Inadequate
Comment: Multiple holes in secondary containment liner/liner needs maintenance				
Corrective Action: The liner will be sufficiently impervious so that any discharge from a primary containment system will not escape containment before cleanup occurs.				Date: 07/23/2023

Venting:

Yes/No	NO	
Comment:		Date:
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	<u>272244</u>	Type:	<u>WELL</u>	API Number:	<u>045-10055</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing, well on plunger lift</u>							Date:	
Corrective Action:								Date:	
Facility ID:	<u>272245</u>	Type:	<u>WELL</u>	API Number:	<u>045-10054</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing, well on plunger lift</u>							Date:	
Corrective Action:								Date:	
Facility ID:	<u>272633</u>	Type:	<u>WELL</u>	API Number:	<u>045-10112</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing, well on plunger lift</u>							Date:	
Corrective Action:								Date:	
Facility ID:	<u>272634</u>	Type:	<u>WELL</u>	API Number:	<u>045-10111</u>	Status:	<u>SI</u>	Insp. Status:	<u>SI</u>
Producing Well									
Comment:	<u>Producing, well on plunger lift</u>							Date:	
Corrective Action:								Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
		Gravel				Sparse
		Ditches				
Gravel						Sparse in areas
Berms						
Compaction						Areas of light compaction
		Compaction				

Comment: Location appears to have some gravel throughout the location with light compaction. Places with sparse to no gravel are present on location. Sparse gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Please refer to Housekeeping & Tanks & Berms for observed compliance issues.	smelserw	10/08/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708901900	Inspection 708901899 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6277197
708901901	Inspection 708901899 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6277198