

# Inspection Photos

Loc: 384227

Operator: WESTERN OPERATING COMPANY

Inspection Date: 10/5/2023

County: Kiowa



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing northwest along the abandoned flowline near the location. There is oily sludge shown at red arrow that needs to be cleaned up. Lat/Long:-38.42686,-102.46158.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:384227 | Date: 10/5/2023

## Inspection Photos



**Photo 2.** View of oily sludge shown at the surface. Lat/Long:38.42686,-102.46158.



## Inspection Photos



**Photo 3.** There is an exposed flowline at the surface that needs to be removed. .  
Lat/Long:38.42686,-102.46158.



## Inspection Photos



**Photo 4.** Facing southwest along the abandoned flowline near the location. There is oily sludge shown at red arrow that needs to be cleaned up. Lat/Long:-38.42686,-102.46158.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:384227 | Date: 10/5/2023

## Inspection Photos



**Photo 5.** Facing southwest near the abandoned wellsite is abandoned flowline cellar that needs to be removed. Lat/Long:38.42706, -102.46211.



## Inspection Photos



**Photo 6.** Facing north at the abandoned wellsite location. The sandy soils have not revegetated and need to be seeded and reclaimed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:384227 | Date: 10/5/2023

## Inspection Photos



**Photo 7.** Facing east at the abandoned wellsite location. The sandy soils have not revegetated and need to be seeded and reclaimed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:384227 | Date: 10/5/2023

## Inspection Photos



**Photo 8.** Facing southwest at the abandoned wellsite location. The sandy soils have not revegetated and need to be seeded and reclaimed. The red arrow points to the abandoned flowline cellar that needs to be removed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:384227 | Date: 10/5/2023