

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/05/2023

Submitted Date:

10/09/2023

Document Number:

710500059

**FIELD INSPECTION FORM**Loc ID 324794 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 16520

Name of Operator: CHEMCO INC

Address: 6970 SOUTH HOLLY CIR STE 206

City: CENTENNIAL State: CO Zip: 80112

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

6 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Neher, Morgan	303-771-7777	morgan@chemco-og.com	
Costa, Ryan		ryan.costa@state.co.us	
Neher, Gray	303-771-7777/9006	bogray@msn.com	
Sanchez, Chris		chris.sanchez@state.co.us	
Welsh, Brian		brian.welsh@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
150026	UIC DISPOSAL	AC	07/25/1980		-	LINCOLN 2	EI
212648	WELL	IJ	02/06/2023	DSPW	061-06008	LINCOLN 2	EI

**General Comment:**

This is an Environmental Inspection for the Lincoln #2 Facility ID 324794, located in Kiowa County, Co

**Location**Overall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Comply with CA's outlined in inspection # 710500056		
Corrective Action:	Comply with Rule 605.h. for Tank and Container labels	Date:	11/08/2023

**Emergency Contact Number:**

Comment:			
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
Produced Water	Tank			
Comment:	At the time of inspection there appeared to be a historical release of produced water from a valve located on Tank # 1, looking north identified in Picture # 2 of location photos. The spill was not active at the time of inspection. Operator shall report and investigate the potential release per Rule 912			
Corrective Action:	Comply with Rule 912			Date: 10/12/2023

In Containment: Yes

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Prime Mover	# 1		corrective date
Comment:	There is an active equipment leak on engine skid located within the Engine Skid Building. There are visual impacts to soil inside Skid Building and daylighting from the Northeast corner of building		
Corrective Action:	Cleanup affected soil and maintain equipment within compliance of rule 608.e		
		Date:	11/08/2023

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 150026 Type: UIC API Number: - Status: AC Insp. Status: EIFacility ID: 212648 Type: WELL API Number: 061-06008 Status: IJ Insp. Status: EI**COGCC Comments**

Comment	User	Date
There is an active equipment leak on engine skid located within the Engine Skid Building. There are visual impacts to soil inside Skid Building and daylighting from the Northeast corner of building.  Cleanup affected soil and maintain equipment within compliance of rule 608.e	sanchezcc	10/09/2023
At the time of inspection there appeared to be a historical release of produced water from a valve located on Tank # 1, looking north identified in Picture # 2 of location photos. The spill was not active at the time of inspection. Operator shall report and investigate the potential release per Rule 912	sanchezcc	10/09/2023

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500060	Location Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6278474">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6278474</a>