



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type WEEDS

Comment: weeds unmanaged on location

Corrective Action: Comply with rule 606

Date: 10/10/2023

Overall Good:

**Spills:**

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

corrective date

Type: Pump Jack # 1

Comment:

Corrective Action:

Date:

Type: Bradenhead # 1

Comment:

Corrective Action:

Date:

Type: Prime Mover # 1

Comment: electric motor

Corrective Action:

Date:

Type: Ancillary equipment # 1

Comment: electric

Corrective Action:

Date:

**Venting:**

Yes/No	NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 202208 Type: WELL API Number: 001-07613 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 05/18/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><a href="#">ECMC Inspection Report Summary</a>                      On 10/3/23 I, Inspector Justin Medina conducted an on-site inspection at:                      Well Name- Albert Sack D 2                      Company Name- KPK                      API- 05-001-07613                      In Adams County Colorado.                      While there, I observed SI well                      During this inspection the following possible compliance issues were observed:                      Weeds. Rule 606. 10/10/23                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.                      This inspection does not nullify any orders or corrective actions from the ECMC.                      At time of inspection weather conditions were warm, partly cloudy, light wind.                      This is a summary of inspection report.</p>	medinaj	10/03/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403549128	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6272601">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6272601</a>
699505042	Inspection pictures	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6272587">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6272587</a>