

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S96W/33SESW

Location ID: 334862

Date: 10/5/2023



Entrance to Location – Photo #06830



Wellheads – Photo #06831

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S96W/33SESW

Location ID: 334862

Date: 10/5/2023



Separators – Photo #06832



Tank Battery – Photo #06833

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S96W/33SESW

Location ID: 334862

Date: 10/5/2023



Location Lacks Stabilization – Photo #06834



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #06835**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S96W/33SESW

Location ID: 334862

Date: 10/5/2023



**Insufficient Erosion Controls/Rill Erosion on Lease Road –
Photo #06836**