

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

10/10/2023

Submitted Date:

10/10/2023

Document Number:

707901159

FIELD INSPECTION FORM
 Loc ID 322261 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 44390

Name of Operator: JAVERNICK OIL

Address: 3040 E MAIN

City: CANON CITY State: CO Zip: 81212

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Javernick, James	719-275-3040/719-671-3787	javernick1@gmail.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210081	WELL	PR	02/01/2022	OW	043-40017	MARJO M2	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	PHOTO 4: Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible (TANK CAPACITY IS NOT POSTED).		
Corrective Action:	THIS IS THE SECOND NOTICE FOR THIS CORRECTIVE ACTION). Install sign to comply with Rule 605.h. IMMEDIATE ACTION IS REQUIRED.	Date:	11/19/2022

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1		STEEL AST		,
Comment:	Gauge hatch open or not sealed.				
Corrective Action:	Close and seal gauge hatches when not accessing tank per Rule 608.a.(9).				Date: 10/11/2023

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
------	--	--

Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 210081 Type: WELL API Number: 043-40017 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: _____ Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: Submit reports

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
ECMC Inspection Report Summary On Tuesday October 10, 2023 at approximately 3:44PM, I, Inspector Randy Silver, conducted an on-site re-inspection per doc#'s 695107123 and 707900074. Location: Marjo #M2 Operator: Javernick Oil API#: 043-40017 County: Freemont While there, I observed a producing well site and facility. During this inspection the following possible compliance issues were observed: Tank labels: Rule 605h Corrective action date of 11-19-22 Guage hatch: Rule 608 a (9) Corrective action date of 10-11-23 Weather conditions: Clear A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.	silverrr	10/10/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707901160	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6279973