

Caerus Piceance LLC  
Piceance Creek Unit-62S97W 2NESW  
Location ID: 335694




Entrance sign at well pad

Access road into well pad

Caerus Piceance LLC  
Piceance Creek Unit-62S97W 2NESW  
Location ID: 335694




Wellhead sign missing required information



Debris

Caerus Piceance LLC  
Piceance Creek Unit-62S97W 2NESW  
Location ID: 335694



Debris



Debris

Caerus Piceance LLC  
Piceance Creek Unit-62S97W 2NESW  
Location ID: 335694



Debris



Debris

Caerus Piceance LLC  
Piceance Creek Unit-62S97W 2NESW  
Location ID: 335694



**Disconnected manifold open to wildlife**

**Rain cap missing on riser**

Caerus Piceance LLC  
Piceance Creek Unit-62S97W 2NESW  
Location ID: 335694



Debris



Rain cap missing on riser

Caerus Piceance LLC  
Piceance Creek Unit-62S97W 2NESW  
Location ID: 335694



**Debris. Box is disconnected.**



**Equipment not in use**

Caerus Piceance LLC  
Piceance Creek Unit-62S97W 2NESW  
Location ID: 335694



**Disconnected manifold open to wildlife**



**Pressure relief risers missing rain caps**

**Caerus Piceance LLC  
Piceance Creek Unit-62S97W 2NESW  
Location ID: 335694**



**Location view from Northwest corner**

**Location view from Southwest corner**

**Caerus Piceance LLC  
Piceance Creek Unit-62S97W 2NESW  
Location ID: 335694**




**Location view from Northeast corner**



**Location view from Southeast corner**

Caerus Piceance LLC  
Piceance Creek Unit-62S97W 2NESW  
Location ID: 335694




Tank battery view from Southeast corner




Tank battery view from Northeast corner

Caerus Piceance LLC  
Piceance Creek Unit-62S97W 2NESW  
Location ID: 335694



Tank battery view from Northwest corner



Tank battery view from Southwest corner