

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/27/2023

Submitted Date:

10/04/2023

Document Number:

696205299

FIELD INSPECTION FORMLoc ID: 312407 Inspector Name: Trujillo, Aaron On-Site Inspection: ☐ 2A Doc Num: **Operator Information:**

OGCC Operator Number: 10150

Name of Operator: BLACK HILLS PLATEAU PRODUCTION LLC

Address: 1515 WYNKOOP ST STE 500

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		randy.harris@blackhillscorp.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221510	WELL	PA	08/21/2013	GW	077-08111	KATHLYN YOUNG 4-15	RI
312407	LOCATION	CL			-	KATHLYN YOUNG-610S95W 15NWSE	RI

General Comment:

On 9/27/2023, Reclamation Specialist Trujillo conducted a final reclamation and stormwater inspection at BLACK HILLS PLATEAU PRODUCTION LLC's Kathlyn Young #4-15 location in Mesa County, Colorado.

This inspection is a follow-up to #696204939 dated 5/15/2023 to document compliance with the following corrective actions:
-Final Reclamation
-Stormwater

It was observed in this inspection that the Location remains out of compliance with ECMC Rules and Corrective Actions.

Refer to the "Reclamation" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable; The "Date of Discovery" is being provided as the corrective action date for all new observed compliance issues. Location will remain out of compliance until corrective action(s) has(have) been resolved and a follow up inspection will be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.

Inspected Facilities									
Facility ID:	221510	Type:	WELL	API Number:	077-08111	Status:	PA	Insp. Status:	RI
Facility ID:	312407	Type:	LOCATION	API Number:	-	Status:	CL	Insp. Status:	RI

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed **Fail** No disturbance /Location never built _____

Access Roads Regraded **Fail** Contoured **Fail** Culverts removed _____

Gravel removed **Fail**

Location and associated production facilities reclaimed **Fail** Locations, facilities, roads, recontoured **Fail**

Compaction alleviation **Fail** Dust and erosion control **Fail**

Non cropland: Revegetated 80% **Fail** Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: [See "COGCC Comments" at the end of this report.](#)

Corrective Action: _____ Date **07/17/2023**

Comply with 1004 Rules and conduct final reclamation on the Location and access road.

Remove unused equipment.

Comply with Rule 1002.f and install and maintain stormwater and erosion control BMPs to minimize erosion, degradation and off-site sediment transport. Ensure BMPs are implemented to stabilize the seeded soils; stormwater management required until Location receives a passing final reclamation inspection.

Overall Final Reclamation

Fail

Well Release on Active Location ☐Multi-Well Location ☐**COGCC Comments**

Comment	User	Date
<p>RECLAMATION COMMENT</p> <p>Inspection #696204939 observed that Final Reclamation was not completed in accordance with 1004 Rules; Location has not been recontoured/regraded and reclaimed. Cut and fill slopes evident; Cut slopes lack stabilization and erosion degradation was observed. A soil stockpile was observed on the southern areas of the Location; segregated soils have not been replaced to their original relative positions and contoured. Gravel and road base material remains apparent on Location; access road has not been decompacted, recontoured/regraded and reclaimed; unused pipe equipment remained stored on the Location.</p> <p>Inspection required Operator to comply with 1004 Rules, and Rule 1002.f.</p> <p>It was observed in this inspection corrective actions to comply with 1004 Rules, and Rule 1002.f have not been taken; Location/access road has not been decompacted, recontoured/regraded and reclaimed; soil stockpile remains on Location. Pipe equipment remains on west end of the Location. Erosion degradation has persisted.</p> <p>Corrective actions has not been addressed and remains applicable.</p>	trujilloam	10/04/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403550105	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6273602
696205300	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6273596