

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/03/2023

Submitted Date:

10/04/2023

Document Number:

712700697

FIELD INSPECTION FORM

Loc ID 325264 Inspector Name: Pattillo, Curtis On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10734
Name of Operator: HIGH RIVER RESOURCES OPERATING LLC
Address: 3838 OAK LAWN AVE SUITE 710
City: DALLAS State: TX Zip: 75219

Findings:

- 27 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Mcdonough, Corey		corey.mcdonough@state.co.us	
Archuleta, Amy		aarchuleta@highriverllc.com	All Inspections
Vaughn, Robert		rvaughn@highriverllc.co	Primary Contact
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214425	WELL	PR	02/01/2019	GW	067-06026	UTE 3	PR

General Comment:

[SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.](#)

Location			
Lease Road:			
Type	Access		
comment:	Dirt and gravel, private property.		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Metal sign posted at wellhead.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Contents and volume labels, NFPA placard on produced water tank.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Warning signs at location entrance. Warning signs on skid compressor.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Posted on wellhead sign.		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	Undesirable vegetation growing near separator and wellhead.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Observed impacted material on ground surrounding skid mounted compressor. Impacted area approximately 10-ft. x 5-ft. See photos #4 & #5.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes.	Date:	10/18/2023
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	TANK BATTERY		
Comment:	T-post and hog wire around produced water tank.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Pipe rail enclosure around above ground valve.		
Corrective Action:		Date:	

Type	OTHER		
Comment:	Pipe rail fencing around skid mount compressor.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Unitized vertical separator/dehydrator skid mounted.		
Corrective Action:		Date:	
Type: Gathering Line	# 1		
Comment:	2" line from meter to above ground valve.		
Corrective Action:		Date:	
Type: Flow Line	# 3		
Comment:	2-2" lines from wellhead to separator. 1-2" line from separator to compressor.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	2" line from separator to digital meter.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead		
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:	Skid mounted		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Accessible		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:	On separator vent stack.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	Open Top		37.006870,-107.636630

Comment:	Screened, open top steel tank.	
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Plastic liner on base.				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	Open Top		37.006950,-107.636650
Comment: Partially buried, plastic liner inside, screened, open top steel tank. Tank is labeled Harvest Midstream.					
Corrective Action:				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 214425 Type: WELL API Number: 067-06026 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 07/10/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Culverts	Pass	Material Handling And Spill Prevention	Pass	Containers within containment.
Compaction	Pass					
Rip Rap	Pass	Gravel	Pass			
Gravel	Pass					
Ditches	Pass	Ditches	Pass			
Waddles	Fail					

Comment: [Numerous wattles missing, numerous old staking protuding. See photo #6.](#)

Corrective Action: [Repair stormwater BMPs, remove staking as debris from old BMP installations.](#)

Date: 10/19/2023

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403550071	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6273577
712700703	Well Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6273570