

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/29SWNE

Location ID: 335298

Date: 10/12/2023



Location Entrance – Photo #06891



Wellheads – Photo #06892

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/29SWNE

Location ID: 335298

Date: 10/12/2023



Separators – Photo #06894



Tank Battery – Photo #06896

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/29SWNE

Location ID: 335298

Date: 10/12/2023



Location Lacks Stabilization – Photo #06895



Location Lacks Stabilization – Photo #06897

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/29SWNE

Location ID: 335298

Date: 10/12/2023



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #06898