

Inspection Photos

Location Name: TEP Rocky Mountain LLC LAST DANCE 9-3 Pad

Location # 324247



Photo # 2208 From entrance to location



Photo # 2209 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC LAST DANCE 9-3 Pad

Location # 324247



Photo # 2210 Location



Photo # 2211 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC LAST DANCE 9-3 Pad

Location # 324247



Photo # 2212 Location



Photo # 2213 Battery sign weathered & illegible

Inspection Photos

Location Name: TEP Rocky Mountain LLC LAST DANCE 9-3 Pad

Location # 324247



Photo # 2214 PRV & rupture disk vent lines lack caps



Photo # 2215 PRV & rupture disk vent lines lack caps

Inspection Photos

Location Name: TEP Rocky Mountain LLC LAST DANCE 9-3 Pad

Location # 324247



Photo # 2216 Unused equipment




Photo # 2217 Unused equipment/ECD is disconnected

Inspection Photos

Location Name: TEP Rocky Mountain LLC LAST DANCE 9-3 Pad

Location # 324247



Photo # 2218 Unused equipment/ECD is disconnected