Inspector Name: Kester, Michael

FORM INSP

> Rev X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109





Inspection Date: 10/13/2023 Submitted Date:

10/13/2023 Document Number:

FIELD INSPECTION FORM

		FIELL	INSPECT	ION FORW			<u>713300203</u>		
Loc ID	Inspector Na	me:	On-Site	Inspection	Stat	Status Summary:			
320114	Kester, Mich	ael	2/	A Doc Num:		THIS IS A FOLLOW UP INSPECTION			
Operator Information:						FOLLOW UP INSPECTION REQUIRED			
OGCC Ope	rator Number:	69175				NO FOLLOW UP INSPECTION REQUIRED			
Name of Op	erator: PDC ENE	RGY INC			Fine	<u>dings:</u>			
A -l -l	000 40711 0707	T CUITE	4500			Number of Comment	S		
Address. 1	099 18TH STREE	ET SUITE	1500			1 Number of Corrective	e Actions		
City:	DENVER	State:	CO	Zip: 8020	<u>)2</u> <u>X</u>	□ Corrective Action Response Requested			
Contact Info	ormation:					ANY CORRECTIVE ACT PREVIOUS INSPECTION BEEN ADDRESSED ARI	NS THÁT HAVE NOT		
Contact Na		Phor	ne	Email		Comment			
Silver, Randy				randy.silver@s	tate.co.us				
, PDC				cogccinspectio					
Inspected F	acilities:								
Facility ID	Туре	Status	Status Date	Well Class	API Num	Facility Name	Insp Status		
202691	WELL	TA	08/18/2020	OW	001-08096	KALCEVIC FARMS	41-3 1 TA		
General Co	mment:								

Inspector Name: Kester, Michael

				<u>Lo</u>	ocation						
Overall Good: 🔀											
Signs/Marker:											
Туре	TANK LABELS/PLACARDS										
Comment:	good										
Corrective Action:			Date	:							
Туре	BATTERY										
Comment:	good										
Corrective Action:	Date:										
Туре	WELLHEAD	WELLHEAD									
Comment:	No well head	sign									
Corrective Action:	Comply with	Rule 605d						Date	: 11/13/2023		
Emergency Contact N	Number:										
Comment:											
Corrective Action:								Date:			
Overall Good: 🔀											
Spills:											
Туре	Area		Volume								
In Containment: N	No										
Comment:											
Multilple Spills a	and Releases	?									
Equipment:									corrective date		
Type: Bird Protectors		#	1								
Comment:											
Corrective Action:	:							Date:			
Type: Deadman # & I	⊥ Marked	#	4								
Comment:											
Corrective Action:								Date:			
Type: Horizontal Hea	ted Separator	#	1								
Comment:											
Corrective Action:								Date:			
Tanks and Berms:											
Contents # Capacity Type Tank ID SE GPS							SE GPS				
CRUDE OIL 1 300 BBLS			STEEL AST ,								
Comment:											
Corrective Action:							Date:				
<u>Paint</u>											
Condition Adequate											
Other (Content)											

Inspector Name: Ke	ester, Michael						
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Туре	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	tenance		
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate			
Comment:							
Corrective Action:					Date:		
<u>Venting:</u>							
Yes/No	NO						
Comment	:						
Corrective Action	:				Date:		
Flaring:							
Туре							
Commen							
Corrective Action	n:				Date:		

Inspector Name: Kester, Michael

Inspected Facilities											
Facility ID: 202	2691	Type: _	WELL	API Number:	001-08096	Status:	TA	Insp.	Status: _	TA	
				Idle V	Well						
Purpose:	Purpose: Shut In										
Comme	ent: TA v	vell									
Corrective Acti	Corrective Action:										
<u>BradenHead</u>											
Date of Last Brhd	Date of Last Brhd Test: 06/14/2023 Annual Brhd Completed? Yes										
Last Brhd Test Re	esults I	nitial Surf	Csg Pressure:		Fluid Type:						
		End Surf C	Ssg Pressure:	0							
Comment	t:										
Corrective Action	n:							Date:			
				COGCC	Comments Comments						
Comment							User		Date		
ECMC Inspection Report Summary On Friday 10-13-2023 at approximately 14:00, I, Inspector Michael Kester, conducted an on-site inspection. Location: Kalcevic Farms 41-31 Operator: PDC API#: 001-08096 County: Adams While there, I observed TA well site and production equipment. During this inspection the following possible compliance issues were observe Sign, Rule 605d corrective action date 11-13-2023 See attached photos Weather conditions: windy, sunny and dry A follow up inspection needed to be conducted to ensure the Compliance to comply with ECMC rules. This is a summary of inspection report. This inspection does not nullify any orders or NOAV from the ECMC This is a continuing education inspection							kestern	n	10/13/202		
Attached Docu		mages (h	ttps://coacc.s	state.co.us/weblir	ok/) and sparch	by document	numbor				
Document Num				JRL	ik) and search	by document	. Humber.	•			
713300206	·							<u>82</u>			